

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
20

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
119

**ROOM NAME**  
Distance Learning

**Status**  
Active

**Use Code**  
530-Audio/Visual, Radio, T

**Use Observed**  
See notes

**TOP/CSS Code**  
6130-Media Services

**Assignable Stations**  
48

**Observed Stations**

**Assignable Area**  
945

**Measured Area**  
905.34

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Not setup for Distance Learning

**Fusion Recommendation**  
Install DL Equip

**Review Date**  
8/9/2018 8:18:06 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id: 25      Campus Name: Fresno City College      Campus Code: 571

Build No: 1      Building Name: HISTORIC OAB      Abbrev: HOAB      Condition: Satisfactory

Fusion Room No: 123      ROOM NAME: Faculty Offices      Status: Active

Use Code: 310-Office      Use Observed: Matches Fusion      TOP/CSS Code: 0099-General Assignment

Assignable Stations: 5      Observed Stations: 4

Assignable Area: 421      Measured Area: 415.84      Unassigned areas were not required to be measured

A/V Equip:      WhiteBoard: No      Seating Type: Desks

Floor Finish: Carpet      Floor Condition: 1

Ceiling Finish: Paint      Ceiling Condition: 1

Wall Finish: Paint      Wall Condition: 1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date: 5/21/2018 11:53:32 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  **Unassigned areas were not required to be measured**

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
29

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
126

**ROOM NAME**  
President

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
See notes

**TOP/CSS Code**  
6620-Management Plannin

**Assignable Stations**  
1

**Observed Stations**  
40

**Assignable Area**  
31

**Measured Area**  
732.6

Unassigned areas were not required to be measured

**A/V Equip**  
Monitor - Polycom System

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Room appears to be a meeting conference room not office

**Fusion Recommendation**  
Reclassify Room to 680 Conference Room

**Review Date**  
5/21/2018 11:53:32 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
31

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
127

**ROOM NAME**  
Distance Learning

**Status**  
Active

**Use Code**  
530-Audio/Visual, Radio, T

**Use Observed**  
See notes

**TOP/CSS Code**  
6130-Media Services

**Assignable Stations**  
36

**Observed Stations**  
37

**Assignable Area**  
706

**Measured Area**  
709.47

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Tackboard

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

Not setup for Distance Learning

**Fusion Recommendation**

Install DL Equip

**Review Date**  
6/8/2018 8:18:27 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
33

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
130

**ROOM NAME**  
Historical Library

**Status**  
Active

**Use Code**  
620-Exhibition

**Use Observed**  
See notes

**TOP/CSS Code**  
6140-Museums and Galleri

**Assignable Stations**

**Observed Stations**  
28

**Assignable Area**  
735

**Measured Area**  
1016.86

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Wood

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Room is a classroom not Museum

**Fusion Recommendation**  
Reclassify Room to 110 Classroom

**Review Date**  
6/8/2018 8:18:27 AM

# 1794 Room Assessment Data

**Id**  
34

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
131

**ROOM NAME**  
Distance Learning

**Status**  
Active

**Use Code**  
530-Audio/Visual, Radio, T

**Use Observed**  
See notes

**TOP/CSS Code**  
6130-Media Services

**Assignable Stations**  
37

**Observed Stations**  
36

**Assignable Area**  
725

**Measured Area**  
715.5

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Wood

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Tackboard

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Not set up for distance-learning

**Fusion Recommendation**  
Install DL Equip

**Review Date**  
5/21/2018 11:53:32 AM



# 1794 Room Assessment Data

**Id**  
35

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
135

**ROOM NAME**  
President's Staff

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
See notes

**TOP/CSS Code**  
6620-Management Plannin

**Assignable Stations**  
2

**Observed Stations**

**Assignable Area**  
313

**Measured Area**  
253.08

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Room appears to be meeting room not an office

**Fusion Recommendation**  
Reclassify Room to 680 Conference Room

**Review Date**  
5/21/2018 11:53:32 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
38

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
139B

**ROOM NAME**  
Museum support

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Unassigned

**TOP/CSS Code**  
6140-Museums and Galleri

**Assignable Stations**  
2

**Observed Stations**

**Assignable Area**  
170

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**

**Floor Condition**

**Ceiling Finish**

**Ceiling Condition**

**Wall Finish**

**Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Could no access room

**Fusion Recommendation**

**Review Date**  
8/10/2018 8:41:06 PM

# 1794 Room Assessment Data

**Id**  
39

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
139C

**ROOM NAME**  
Museum Storage

**Status**  
Active

**Use Code**  
625-Exhibition Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6140-Museums and Galleri

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
19

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**

**Floor Condition**

**Ceiling Finish**

**Ceiling Condition**

**Wall Finish**

**Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
could not access room

**Fusion Recommendation**

**Review Date**  
8/10/2018 8:41:28 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
44

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
142

**ROOM NAME**  
Does not exist in the Building or Plans

**Status**  
Active

**Use Code**  
110-Classroom

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
80

**Observed Stations**

**Assignable Area**  
1652

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**

**Floor Condition**

**Ceiling Finish**

**Ceiling Condition**

**Wall Finish**

**Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/2/2018 5:50:39 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
47

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
147

**ROOM NAME**  
PIO

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
See notes

**TOP/CSS Code**  
6710-Community Relations

**Assignable Stations**  
3

**Observed Stations**

**Assignable Area**  
323

**Measured Area**  
309.75

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Room is used as storage not office

**Fusion Recommendation**  
Reclassify Room to 730-Storage

**Review Date**  
5/21/2018 11:53:32 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
72

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
H170

**ROOM NAME**  
Corridor

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
2758

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
5/21/2018 1:46:10 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
74

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
171

**ROOM NAME**  
Interdisciplinary

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
See notes

**TOP/CSS Code**  
4900-Interdisciplinary Studi

**Assignable Stations**  
38

**Observed Stations**  
39

**Assignable Area**  
706

**Measured Area**  
714.23

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
appears to be a lecture room as opposed to a lab

**Fusion Recommendation**  
Reclassify Room to 110 Classroom

**Review Date**  
5/21/2018 11:53:32 AM



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
80

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
176

**ROOM NAME**  
Interdisciplinary

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
See notes

**TOP/CSS Code**  
4900-Interdisciplinary Studi

**Assignable Stations**  
49

**Observed Stations**  
50

**Assignable Area**  
960

**Measured Area**  
941.8

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Tackboard

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

## Observed Defects

## Assessment

Room use looks like classroom not a class lab

## Fusion Recommendation

Reclassify Room to 110 Classroom

## Review Date

8/9/2018 8:20:28 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  **Unassigned areas were not required to be measured**

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
97

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
194A

**ROOM NAME**  
Music toilet

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
45

**Measured Area**  
45.5

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Tile

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
5/21/2018 12:22:33 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
100

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
194C

**ROOM NAME**  
Music toilet

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
45

**Measured Area**  
45.5

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Tile

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
5/21/2018 1:38:16 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
102

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
198

**ROOM NAME**  
Music Lab

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**  
91

**Observed Stations**

**Assignable Area**  
1120

**Measured Area**  
1116.49

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Chairs -movable

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
5/21/2018 12:28:05 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
108

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
217

**ROOM NAME**  
Interdisc Lab

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
4930-General Studies

**Assignable Stations**  
48

**Observed Stations**  
48

**Assignable Area**  
963

**Measured Area**  
932.52

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Tackboard

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 2:23:09 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
131

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
241

**ROOM NAME**  
Dean of Instruction staff

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6010-Academic Administra

**Assignable Stations**  
6

**Observed Stations**

**Assignable Area**  
695

**Measured Area**  
629.09

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/8/2018 8:36:33 AM

# 1794 Room Assessment Data

**Id**  
132

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
243A

**ROOM NAME**  
DOI work room

**Status**  
Active

**Use Code**  
315-Office Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6010-Academic Administra

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
410

**Measured Area**  
291.25

Unassigned areas were not required to be measured

**A/V Equip**  
Monitor - Polycom System

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/8/2018 8:40:20 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
137

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
247B

**ROOM NAME**  
Janitor

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
29

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sheet Vinyl

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/25/2018 2:51:03 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
143

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
250

**ROOM NAME**  
Auditorium, balcony seating

**Status**  
Active

**Use Code**  
610-Assembly

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6830-Community Use of Fa

**Assignable Stations**  
108

**Observed Stations**  
99

**Assignable Area**  
970

**Measured Area**  
946.83

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Wood

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/8/2018 8:18:27 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
147

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
253

**ROOM NAME**  
Meeting Service

**Status**  
Active

**Use Code**  
685-Meeting Room Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6830-Community Use of Fa

**Assignable Stations**  
2

**Observed Stations**

**Assignable Area**  
165

**Measured Area**  
146

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/8/2018 8:18:27 AM

# 1794 Room Assessment Data

**Id**  
148

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
253A

**ROOM NAME**  
Storage

**Status**  
Active

**Use Code**  
730-Storage

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6770-Logistical Services

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
137

**Measured Area**  
147.84

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/25/2018 2:55:22 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
157

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
261

**ROOM NAME**  
PA

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1007-Dramatic Arts

**Assignable Stations**  
2

**Observed Stations**

**Assignable Area**  
202

**Measured Area**  
172.38

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/8/2018 8:18:27 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
164

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
271B

**ROOM NAME**  
Entry

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
137

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sheet Vinyl

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/8/2018 8:18:27 AM

# 1794 Room Assessment Data

**Id**  
165

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
271

**ROOM NAME**  
Large Group Instruction

**Status**  
Active

**Use Code**  
110-Classroom

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
80

**Observed Stations**  
100

**Assignable Area**  
1652

**Measured Area**  
1523.34

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Chairs-fixed

**Floor Finish**  
Sheet Vinyl

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/8/2018 8:18:27 AM

# 1794 Room Assessment Data

**Id**  
166

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
272

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
310 Office

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
5

**Observed Stations**  
5

**Assignable Area**  
378

**Measured Area**  
367.5

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Square footage calculated based on calculation

**Fusion Recommendation**

**Review Date**  
6/8/2018 8:18:27 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
168

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
274

**ROOM NAME**  
Interdisciplinary

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
See notes

**TOP/CSS Code**  
4900-Interdisciplinary Studi

**Assignable Stations**  
47

**Observed Stations**  
47

**Assignable Area**  
933

**Measured Area**  
916.45

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Sheet Vinyl

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Tackboard

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Observe use in room is a classroom does not appear to be an interdisciplinary lab

**Fusion Recommendation**  
Reclassify Room to 110 Classroom

**Review Date**  
6/8/2018 8:18:27 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
172

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
277B

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
2

**Observed Stations**  
1

**Assignable Area**  
121

**Measured Area**  
113.32

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/8/2018 8:18:27 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
174

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
1

**Building Name**  
HISTORIC OAB

**Abbrev**  
HOAB

**Condition**  
Satisfactory

**Fusion Room No**  
278

**ROOM NAME**  
Interdisciplinary

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
See notes

**TOP/CSS Code**  
4900-Interdisciplinary Studi

**Assignable Stations**  
47

**Observed Stations**  
50

**Assignable Area**  
918

**Measured Area**  
901.15

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Sheet Vinyl

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Tackboard

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

## Observed Defects

## Assessment

Observe use in room does not appear to be at his interdisciplinary computer lab it is a classroom

## Fusion Recommendation

Reclassify Room to 110 Classroom

## Review Date

6/8/2018 8:18:27 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
188

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
4

**Building Name**  
GYM

**Abbrev**  
G

**Condition**  
Remodeling - C

**Fusion Room No**  
6

**ROOM NAME**  
Hall

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
396

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 5:35:10 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
190

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
4

**Building Name**  
GYM

**Abbrev**  
G

**Condition**  
Remodeling - C

**Fusion Room No**  
12

**ROOM NAME**  
Main Gym

**Status**  
Active

**Use Code**  
520-Athletics/Physical Educ

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
15982

**Measured Area**  
15872

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**  
Bleachers

**Floor Finish**  
Wood

**Floor Condition**  
4

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 5:44:23 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
194

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
4

**Building Name**  
GYM

**Abbrev**  
G

**Condition**  
Remodeling - C

**Fusion Room No**  
100H

**ROOM NAME**  
Staff Restroom, Coaches

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
148

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Tile

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 11:18:59 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
199

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
4

**Building Name**  
GYM

**Abbrev**  
G

**Condition**  
Remodeling - C

**Fusion Room No**  
100D

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
77

**Measured Area**  
75.6

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 11:20:43 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
201

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
4

**Building Name**  
GYM

**Abbrev**  
G

**Condition**  
Remodeling - C

**Fusion Room No**  
100F

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**  
1

**Observed Stations**  
2

**Assignable Area**  
154

**Measured Area**  
152.47

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 7:14:25 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
217

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
4

**Building Name**  
GYM

**Abbrev**  
G

**Condition**  
Remodeling - C

**Fusion Room No**  
106C

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**  
2

**Observed Stations**  
1

**Assignable Area**  
88

**Measured Area**  
79.8

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 6:30:09 PM

# 1794 Room Assessment Data

Id: 218    Campus Name: Fresno City College    Campus Code: 571

Build No: 4    Building Name: GYM    Abbrev: G    Condition: Remodeling - C

Fusion Room No: 106D    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 0835-Physical Education

Assignable Stations: 2    Observed Stations: 1

Assignable Area: 77    Measured Area: 76.96    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Sealed Concrete    Floor Condition: 1

Ceiling Finish: ACT    Ceiling Condition: 3

Wall Finish: Paint    Wall Condition: 3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/20/2018 6:31:23 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
222

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
4

**Building Name**  
GYM

**Abbrev**  
G

**Condition**  
Remodeling - C

**Fusion Room No**  
G108

**ROOM NAME**

**Status**  
Active

**Use Code**  
525-Athletic/Physical Ed Se

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**  
0

**Observed Stations**

**Assignable Area**  
256

**Measured Area**  
295.68

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Rubber

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
4

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 6:41:40 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
227

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
4

**Building Name**  
GYM

**Abbrev**  
G

**Condition**  
Remodeling - C

**Fusion Room No**  
1092

**ROOM NAME**  
Storage

**Status**  
Active

**Use Code**  
730-Storage

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
85

**Measured Area**  
84.5

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 11:36:38 AM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
230

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
4

**Building Name**  
GYM

**Abbrev**  
G

**Condition**  
Remodeling - C

**Fusion Room No**  
112

**ROOM NAME**

**Status**  
Active

**Use Code**  
110-Classroom

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
48

**Observed Stations**  
30

**Assignable Area**  
768

**Measured Area**  
750

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 6:09:47 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id: 244    Campus Name: Fresno City College    Campus Code: 571

Build No: 5    Building Name: LIBRARY    Abbrev: L    Condition: Remodeling - A

Fusion Room No: 1    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: See notes    TOP/CSS Code: 4930-General Studies

Assignable Stations: 1    Observed Stations:

Assignable Area: 99    Measured Area: 98.31    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type: Desks

Floor Finish: Carpet    Floor Condition: 1

Ceiling Finish: ACT    Ceiling Condition: 2

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment: Did not find this Room on Plan or in Building

Fusion Recommendation: Delete Room In Fusion

Review Date: 6/25/2018 3:01:42 PM



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
269

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
5

**Building Name**  
LIBRARY

**Abbrev**  
L

**Condition**  
Remodeling - A

**Fusion Room No**  
111

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6120-Library

**Assignable Stations**  
2

**Observed Stations**  
1

**Assignable Area**  
208

**Measured Area**  
224

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**  
Yes

**Seating Type**  
Desks

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/15/2018 11:50:10 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
277

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
5

**Building Name**  
LIBRARY

**Abbrev**  
L

**Condition**  
Remodeling - A

**Fusion Room No**  
118A

**ROOM NAME**  
IDF Room

**Status**  
Active

**Use Code**  
710-Data Processing/Comp

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6780-Management Inform

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
463

**Measured Area**  
463.08

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/22/2018 7:48:33 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
287

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
5

**Building Name**  
LIBRARY

**Abbrev**  
L

**Condition**  
Remodeling - A

**Fusion Room No**  
124A

**ROOM NAME**  
Storage

**Status**  
Active

**Use Code**  
735-Storage Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6130-Media Services

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
201

**Measured Area**  
192.6

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/22/2018 7:48:33 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
294

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
5

**Building Name**  
LIBRARY

**Abbrev**  
L

**Condition**  
Remodeling - A

**Fusion Room No**  
128

**ROOM NAME**  
Office

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6130-Media Services

**Assignable Stations**  
2

**Observed Stations**  
1

**Assignable Area**  
99

**Measured Area**  
96.28

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/22/2018 7:48:33 PM

# 1794 Room Assessment Data

**Id**  
295

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
5

**Building Name**  
LIBRARY

**Abbrev**  
L

**Condition**  
Remodeling - A

**Fusion Room No**  
129

**ROOM NAME**

**Status**  
Active

**Use Code**  
530-Audio/Visual, Radio, T

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6130-Media Services

**Assignable Stations**

**Observed Stations**  
6

**Assignable Area**  
595

**Measured Area**  
596.24

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/22/2018 7:48:33 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id: 297    Campus Name: Fresno City College    Campus Code: 571

Build No: 5    Building Name: LIBRARY    Abbrev: L    Condition: Remodeling - A

Fusion Room No: 130A    ROOM NAME: Computer Repair/New Computer soft    Status: Active

Use Code: 715-DP/Computer Service    Use Observed: Matches Fusion    TOP/CSS Code: 6780-Management Inform

Assignable Stations: 2    Observed Stations:

Assignable Area: 502    Measured Area: 366.7    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: VCT    Floor Condition: 2

Ceiling Finish: ACT    Ceiling Condition: 2

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 6/22/2018 7:48:33 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
303

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
5

**Building Name**  
LIBRARY

**Abbrev**  
L

**Condition**  
Remodeling - A

**Fusion Room No**  
135A

**ROOM NAME**  
Hallway

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
303

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/22/2018 7:48:33 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
306

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
5

**Building Name**  
LIBRARY

**Abbrev**  
L

**Condition**  
Remodeling - A

**Fusion Room No**  
135

**ROOM NAME**

**Status**  
Active

**Use Code**  
410-Read/Study Room

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6120-Library

**Assignable Stations**  
78

**Observed Stations**  
56

**Assignable Area**  
1550

**Measured Area**  
1562

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Wood

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This is the mezzanine at room 134 on the plan

**Fusion Recommendation**

**Review Date**  
6/25/2018 10:16:15 AM

# 1794 Room Assessment Data

**Id**  
307

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
5

**Building Name**  
LIBRARY

**Abbrev**  
L

**Condition**  
Remodeling - A

**Fusion Room No**  
136

**ROOM NAME**

**Status**  
Active

**Use Code**  
530-Audio/Visual, Radio, T

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6130-Media Services

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
472

**Measured Area**  
488

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/22/2018 7:48:33 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
314

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
5

**Building Name**  
LIBRARY

**Abbrev**  
L

**Condition**  
Remodeling - A

**Fusion Room No**  
144

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6110-Learning Center (Lear

**Assignable Stations**  
2

**Observed Stations**  
1

**Assignable Area**  
92

**Measured Area**  
110.09

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**  
Desks

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/22/2018 7:48:33 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
319

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
5

**Building Name**  
LIBRARY

**Abbrev**  
L

**Condition**  
Remodeling - A

**Fusion Room No**  
148

**ROOM NAME**  
DSPS Computer Lab

**Status**  
Active

**Use Code**  
530-Audio/Visual, Radio, T

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6130-Media Services

**Assignable Stations**  
25

**Observed Stations**  
36

**Assignable Area**  
1152

**Measured Area**  
1099.26

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/22/2018 7:48:33 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
337

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
5

**Building Name**  
LIBRARY

**Abbrev**  
L

**Condition**  
Remodeling - A

**Fusion Room No**  
209

**ROOM NAME**  
Men's Restroom

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
106

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Tile

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/22/2018 5:26:33 PM

# 1794 Room Assessment Data

**Id**  
338

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
5

**Building Name**  
LIBRARY

**Abbrev**  
L

**Condition**  
Remodeling - A

**Fusion Room No**  
210

**ROOM NAME**  
Room

**Status**  
Active

**Use Code**  
440-Processing Room

**Use Observed**  
See notes

**TOP/CSS Code**  
6120-Library

**Assignable Stations**  
49

**Observed Stations**

**Assignable Area**  
1087

**Measured Area**  
1185.6

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
No

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This room is now a computer lab

**Fusion Recommendation**  
Reclassify Room to 210 Interdisciplinary Lab

**Review Date**  
6/22/2018 5:08:42 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
344

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
AD4C

**ROOM NAME**  
Staff Restroom, Women

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
77

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Tile

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 7:27:21 AM

# 1794 Room Assessment Data

**Id**  
345

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
AD4A

**ROOM NAME**  
Hallway

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
128

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Wood

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 7:28:08 AM

# 1794 Room Assessment Data

**Id**  
346

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
AD4

**ROOM NAME**

**Status**  
Active

**Use Code**  
315-Office Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6010-Academic Administra

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
204

**Measured Area**  
202.52

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 7:25:10 AM

# 1794 Room Assessment Data

**Id**  
347

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
AD4B

**ROOM NAME**  
Staff Restroom, Men

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
56

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Tile

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 7:26:17 AM

# 1794 Room Assessment Data

**Id**  
348

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
AD5

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6010-Academic Administra

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
145

**Measured Area**  
179.4

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 7:30:07 AM

# 1794 Room Assessment Data

**Id**  
349

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
AD6

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6010-Academic Administra

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
94

**Measured Area**  
146.64

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 7:31:10 AM



# 1794 Room Assessment Data

**Id**  
350

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
AD7

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6010-Academic Administra

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
135

**Measured Area**  
118.56

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 7:32:47 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
354

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
AD11

**ROOM NAME**

**Status**  
Active

**Use Code**  
680-Meeting Room

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6010-Academic Administra

**Assignable Stations**  
15

**Observed Stations**  
1

**Assignable Area**  
252

**Measured Area**  
256

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 7:38:31 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
356

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS100A

**ROOM NAME**  
Service Hall

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
847

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 7:47:41 AM

# 1794 Room Assessment Data

**Id**  
357

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS100

**ROOM NAME**

**Status**  
Active

**Use Code**  
110-Classroom

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
64

**Observed Stations**  
73

**Assignable Area**  
961

**Measured Area**  
930

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Chairs-fixed

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 7:45:52 AM



# 1794 Room Assessment Data

**Id**  
358

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS101A

**ROOM NAME**  
Main Lobby

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
2237

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 7:48:29 AM

# 1794 Room Assessment Data

**Id**  
359

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS101

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1225-Radiologic Technolog

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
80

**Measured Area**  
80

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 7:50:54 AM

# 1794 Room Assessment Data

**Id**  
360

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS103

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1225-Radiologic Technolog

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
80

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 7:52:11 AM

# 1794 Room Assessment Data

**Id**  
361

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS105

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
80

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 7:53:11 AM

# 1794 Room Assessment Data

**Id**  
362

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS107

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
80

**Measured Area**  
80

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
5

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**  
Room appears to be in the state of remodeling

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 7:54:30 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
366

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS110A

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1225-Radiologic Technolog

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
261

**Measured Area**  
253

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 8:01:58 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
374

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS129

**ROOM NAME**  
Dark Room

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1225-Radiologic Technolog

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
280

**Measured Area**  
216.2

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 8:04:00 AM

# 1794 Room Assessment Data

**Id**  
375

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS130

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1240-Dental Occupations

**Assignable Stations**  
30

**Observed Stations**

**Assignable Area**  
2465

**Measured Area**  
2623

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 8:25:44 AM

# 1794 Room Assessment Data

**Id**  
376

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS130B

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1240-Dental Occupations

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
245

**Measured Area**  
240.25

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 8:50:30 AM

# 1794 Room Assessment Data

**Id**  
377

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS130C

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1240-Dental Occupations

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
156

**Measured Area**  
157.59

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 8:29:59 AM

# 1794 Room Assessment Data

**Id**  
378

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS130D

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1240-Dental Occupations

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
124

**Measured Area**  
123

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 8:31:45 AM

# 1794 Room Assessment Data

**Id**  
379

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS130E

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1240-Dental Occupations

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
124

**Measured Area**  
124

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 8:32:38 AM

# 1794 Room Assessment Data

**Id**  
380

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS130F

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1240-Dental Occupations

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
86

**Measured Area**  
82.4

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 8:34:12 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
385

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS132

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1240-Dental Occupations

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
149

**Measured Area**  
180

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 8:41:21 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
387

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS135

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1240-Dental Occupations

**Assignable Stations**  
2

**Observed Stations**

**Assignable Area**  
108

**Measured Area**  
120

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 8:44:13 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
389

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS139

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1240-Dental Occupations

**Assignable Stations**  
2

**Observed Stations**

**Assignable Area**  
108

**Measured Area**  
120

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 8:49:23 AM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
391

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS142

**ROOM NAME**  
Dental Hygiene Dark Room

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1240-Dental Occupations

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
118

**Measured Area**  
116.8

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 8:20:50 AM

# 1794 Room Assessment Data

**Id**  
392

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS144

**ROOM NAME**  
Men's Locker Room

**Status**  
Active

**Use Code**  
690-Locker Room

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1240-Dental Occupations

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
193

**Measured Area**  
193.2

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
4

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Tile

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 8:17:53 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
399

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS150F

**ROOM NAME**  
Janitor

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 9:07:54 AM

# 1794 Room Assessment Data

Id: 400    Campus Name: Fresno City College    Campus Code: 571

Build No: 6    Building Name: HEALTH SCIENCES    Abbrev: HSCI    Condition: Satisfactory

Fusion Room No: HS150    ROOM NAME:    Status: Active

Use Code: 110-Classroom    Use Observed: Matches Fusion    TOP/CSS Code: 0099-General Assignment

Assignable Stations: 139    Observed Stations: 153

Assignable Area: 1552    Measured Area: 1560    Unassigned areas were not required to be measured

A/V Equip: Projector and Screen    WhiteBoard: Yes    Seating Type: Chairs-fixed

Floor Finish: Carpet    Floor Condition: 1

Ceiling Finish: Paint    Ceiling Condition: 2

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date: 8/9/2018 8:55:41 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
402

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS151

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
80.58

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 9:17:51 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
417

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS201B

**ROOM NAME**  
Women's Restroom

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
203

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Tile

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 2:41:30 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
426

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS220C

**ROOM NAME**  
Mech/Roof Access/Water Heater

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 7:09:03 AM

# 1794 Room Assessment Data

**Id**  
427

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS220

**ROOM NAME**

**Status**  
Active

**Use Code**  
230-Individual Study Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
4930-General Studies

**Assignable Stations**  
25

**Observed Stations**  
40

**Assignable Area**  
715

**Measured Area**  
726

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 2:41:30 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  
430

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS224

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
86

**Measured Area**  
85

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 2:41:30 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
436

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS240A

**ROOM NAME**

**Status**  
Active

**Use Code**  
680-Meeting Room

**Use Observed**  
See notes

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
6

**Observed Stations**

**Assignable Area**  
141

**Measured Area**  
140

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Room is not meeting but student testing

**Fusion Recommendation**  
Reclassify Room to 410 Read-Study Room

**Review Date**  
8/9/2018 2:41:30 PM

# 1794 Room Assessment Data

**Id**  
437

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS240B

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1230-Nursing

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
121

**Measured Area**  
120

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 2:41:30 PM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
440

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS240E

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1230-Nursing

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
69

**Measured Area**  
71.25

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 2:41:30 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
442

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS240G

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1230-Nursing

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
343

**Measured Area**  
348

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 2:41:30 PM

# 1794 Room Assessment Data

**Id**  
443

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS240H

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1230-Nursing

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
20

**Measured Area**  
20

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 2:41:30 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
445

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS240J

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1230-Nursing

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
46

**Measured Area**  
45.6

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 2:41:30 PM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
447

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS245

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1230-Nursing

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
225

**Measured Area**  
228

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 2:41:30 PM

# 1794 Room Assessment Data

**Id**  
448

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS250

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1230-Nursing

**Assignable Stations**  
40

**Observed Stations**  
67

**Assignable Area**  
1150

**Measured Area**  
1152

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Desks

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 7:39:26 AM

# 1794 Room Assessment Data

**Id**  
449

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS250A

**ROOM NAME**  
Storage

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1230-Nursing

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
90

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**

**Floor Condition**

**Ceiling Finish**

**Ceiling Condition**

**Wall Finish**

**Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Could not get into these room

**Fusion Recommendation**

**Review Date**  
8/10/2018 8:10:20 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
452

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS255

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
82

**Measured Area**  
80.8

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/9/2018 2:41:30 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
457

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS262

**ROOM NAME**

**Status**  
Active

**Use Code**  
650-Lounge

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6999-Other Ancillary Servic

**Assignable Stations**  
17

**Observed Stations**

**Assignable Area**  
259

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**

**Floor Condition**

**Ceiling Finish**

**Ceiling Condition**

**Wall Finish**

**Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Room 262 years now route 261 and I believe 255 is taken over by telecom room

**Fusion Recommendation**

**Review Date**  
8/10/2018 7:47:58 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id: 460    Campus Name: Fresno City College    Campus Code: 571

Build No: 6    Building Name: HEALTH SCIENCES    Abbrev: HSCI    Condition: Satisfactory

Fusion Room No: HS267    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 1230-Nursing

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 79    Measured Area: 79    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Carpet    Floor Condition: 3

Ceiling Finish: ACT    Ceiling Condition: 2

Wall Finish: Tackboard    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 8/10/2018 8:09:33 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
464

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS270B

**ROOM NAME**  
Hall

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
360

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 8:09:33 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id: 469    Campus Name: Fresno City College    Campus Code: 571

Build No: 6    Building Name: HEALTH SCIENCES    Abbrev: HSCI    Condition: Satisfactory

Fusion Room No: HS280B    ROOM NAME:    Status: Active

Use Code: 215-Class Lab Service    Use Observed: Matches Fusion    TOP/CSS Code: 1230-Nursing

Assignable Stations: 1    Observed Stations:

Assignable Area: 84    Measured Area: 86.11    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: VCT    Floor Condition: 2

Ceiling Finish: ACT    Ceiling Condition: 2

Wall Finish: Paint    Wall Condition: 3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 8/10/2018 7:50:26 AM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  **Unassigned areas were not required to be measured**

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  
478

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
6

**Building Name**  
HEALTH SCIENCES

**Abbrev**  
HSCI

**Condition**  
Satisfactory

**Fusion Room No**  
HS295

**ROOM NAME**

**Status**  
Active

**Use Code**  
650-Lounge

**Use Observed**  
See notes

**TOP/CSS Code**  
6750-Staff Development

**Assignable Stations**  
6

**Observed Stations**  
3

**Assignable Area**  
185

**Measured Area**  
190.3

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This room is now an office

**Fusion Recommendation**  
Reclassify Room to 310 Office

**Review Date**  
8/10/2018 7:46:39 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
485

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
103

**ROOM NAME**  
Customer Service

**Status**  
Active

**Use Code**  
660-Merchandise Facility

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6910-Bookstore

**Assignable Stations**  
2

**Observed Stations**

**Assignable Area**  
70

**Measured Area**  
72

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 9:26:32 AM

# 1794 Room Assessment Data

**Id**  
486

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
104

**ROOM NAME**  
Elevator Lobby

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
175

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
2

**Ceiling Finish**

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 4:05:07 PM



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
489

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
107

**ROOM NAME**

**Status**  
Deactivated

**Use Code**  
630-Food Facilities

**Use Observed**  
See notes

**TOP/CSS Code**  
6450-Student Personnel Ad

**Assignable Stations**  
40

**Observed Stations**

**Assignable Area**  
1058

**Measured Area**  
1280

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Deactivated this is the ram pantry

**Fusion Recommendation**  
Deactivate this room

**Review Date**  
7/31/2018 4:19:24 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
496

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
113

**ROOM NAME**  
Checkout

**Status**  
Active

**Use Code**  
660-Merchandise Facility

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6910-Bookstore

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
643

**Measured Area**  
657

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 9:29:09 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
498

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
115

**ROOM NAME**

**Status**  
Active

**Use Code**  
660-Merchandise Facility

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6910-Bookstore

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
1339

**Measured Area**  
1392

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 9:32:44 AM

# 1794 Room Assessment Data

**Id**  
499

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
116

**ROOM NAME**  
Circulation

**Status**  
Active

**Use Code**  
660-Merchandise Facility

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6910-Bookstore

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
1244

**Measured Area**  
1216

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 9:35:55 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
505

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
121

**ROOM NAME**

**Status**  
Active

**Use Code**  
665-Merchandise Facility S

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6910-Bookstore

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
158

**Measured Area**  
147

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 9:46:59 AM

# 1794 Room Assessment Data

**Id**  
506

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
122

**ROOM NAME**  
Work Room

**Status**  
Active

**Use Code**  
665-Merchandise Facility S

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6910-Bookstore

**Assignable Stations**  
4

**Observed Stations**

**Assignable Area**  
150

**Measured Area**  
150

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 9:56:46 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
508

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
124

**ROOM NAME**

**Status**  
Active

**Use Code**  
660-Merchandise Facility

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6910-Bookstore

**Assignable Stations**  
3

**Observed Stations**

**Assignable Area**  
3217

**Measured Area**  
3203.2

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 9:50:42 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
514

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
127

**ROOM NAME**

**Status**  
Active

**Use Code**  
665-Merchandise Facility S

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6910-Bookstore

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
180

**Measured Area**  
186

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 9:58:08 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
517

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
129

**ROOM NAME**  
Cafe Storage

**Status**  
Deactivated

**Use Code**  
635-Food Facilities Service

**Use Observed**  
See notes

**TOP/CSS Code**  
6450-Student Personnel Ad

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
181

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**

**Floor Condition**

**Ceiling Finish**

**Ceiling Condition**

**Wall Finish**

**Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**  
Deactivate this room

**Review Date**  
8/8/2018 10:05:13 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
530

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
A213

**ROOM NAME**  
Psych Services Conference

**Status**  
Active

**Use Code**  
350-Conference Room

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6499-Other Student Servic

**Assignable Stations**  
10

**Observed Stations**  
16

**Assignable Area**  
216

**Measured Area**  
217.1

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 4:51:54 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
533

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
A215A

**ROOM NAME**  
Psych Services Office

**Status**  
Active

**Use Code**  
540-Clinic St Care

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6499-Other Student Servic

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
78.75

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 4:59:08 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
539

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
A219

**ROOM NAME**  
Upward Bound Office

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6399-Other Counseling and

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
77

**Measured Area**  
82

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**  
Desks

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 5:06:19 PM

# 1794 Room Assessment Data

**Id**  
540

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
A223

**ROOM NAME**  
USEAA Office

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6499-Other Student Servic

**Assignable Stations**  
2

**Observed Stations**

**Assignable Area**  
80

**Measured Area**  
82.95

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 5:12:54 PM

# 1794 Room Assessment Data

**Id**  
541

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
A223A

**ROOM NAME**  
Storage for USEAA

**Status**  
Active

**Use Code**  
730-Storage

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6499-Other Student Servic

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
23

**Measured Area**  
24

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 5:11:33 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
547

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
7

**Building Name**  
STUDENT CENTER

**Abbrev**  
S

**Condition**  
Remodeling - B

**Fusion Room No**  
A229

**ROOM NAME**  
Sign Language Coordinator

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6499-Other Student Servic

**Assignable Stations**  
5

**Observed Stations**  
5

**Assignable Area**  
315

**Measured Area**  
317.52

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**  
Desks

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 5:19:58 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
550

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
8

**Building Name**  
APPLIED TECH 100

**Abbrev**  
AT100

**Condition**  
Remodeling - B

**Fusion Room No**  
100A

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
1

**Observed Stations**  
2

**Assignable Area**  
104

**Measured Area**  
96.6

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 7:50:39 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
552

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
8

**Building Name**  
APPLIED TECH 100

**Abbrev**  
AT100

**Condition**  
Remodeling - B

**Fusion Room No**  
100B

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
4

**Observed Stations**  
2

**Assignable Area**  
411

**Measured Area**  
404.15

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 7:54:54 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  
560

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
8

**Building Name**  
APPLIED TECH 100

**Abbrev**  
AT100

**Condition**  
Remodeling - B

**Fusion Room No**  
100K

**ROOM NAME**

**Status**  
Active

**Use Code**  
680-Meeting Room

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
18

**Observed Stations**  
8

**Assignable Area**  
267

**Measured Area**  
260.96

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 8:05:49 AM

# 1794 Room Assessment Data

**Id**  
561

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
8

**Building Name**  
APPLIED TECH 100

**Abbrev**  
AT100

**Condition**  
Remodeling - B

**Fusion Room No**  
100L

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
See notes

**TOP/CSS Code**  
6010-Academic Administra

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
88

**Measured Area**  
84.75

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Room is Office service not office

**Fusion Recommendation**  
Reclassify Room to 315 Office Service

**Review Date**  
9/3/2018 8:12:13 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
563

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
8

**Building Name**  
APPLIED TECH 100

**Abbrev**  
AT100

**Condition**  
Remodeling - B

**Fusion Room No**  
101A

**ROOM NAME**  
Used for Communications Classes 201

**Status**  
Active

**Use Code**  
110-Classroom

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
4930-General Studies

**Assignable Stations**  
25

**Observed Stations**

**Assignable Area**  
442

**Measured Area**  
403.09

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 8:20:50 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
569

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
8

**Building Name**  
APPLIED TECH 100

**Abbrev**  
AT100

**Condition**  
Remodeling - B

**Fusion Room No**  
104B

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
See notes

**TOP/CSS Code**  
0956-Manufacturing and In

**Assignable Stations**  
2

**Observed Stations**

**Assignable Area**  
176

**Measured Area**  
175

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Wood

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Not office tool storage

**Fusion Recommendation**  
Reclassify Room to 310 Office

**Review Date**  
9/3/2018 8:41:20 AM

# 1794 Room Assessment Data

**Id**  
570

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
8

**Building Name**  
APPLIED TECH 100

**Abbrev**  
AT100

**Condition**  
Remodeling - B

**Fusion Room No**  
104C

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0956-Manufacturing and In

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
258

**Measured Area**  
255

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Wood

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 8:41:58 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
577

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
8

**Building Name**  
APPLIED TECH 100

**Abbrev**  
AT100

**Condition**  
Remodeling - B

**Fusion Room No**  
108

**ROOM NAME**  
Welding Lab

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0956-Manufacturing and In

**Assignable Stations**  
25

**Observed Stations**

**Assignable Area**  
2704

**Measured Area**  
2638.85

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Exposed Structure

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 8:53:47 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
581

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
8

**Building Name**  
APPLIED TECH 100

**Abbrev**  
AT100

**Condition**  
Remodeling - B

**Fusion Room No**  
110B

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0956-Manufacturing and In

**Assignable Stations**  
3

**Observed Stations**

**Assignable Area**  
320

**Measured Area**  
320.76

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 9:03:20 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
595

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
9

**Building Name**  
APPLIED TECH 200

**Abbrev**  
AT200

**Condition**  
Remodeling - C

**Fusion Room No**  
D102

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
See notes

**TOP/CSS Code**  
7010-Auxiliary Classes

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
113

**Measured Area**  
109.2

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This room is a store room

**Fusion Recommendation**  
Reclassify Room to 315 Office Service

**Review Date**  
8/10/2018 6:44:39 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
597

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
9

**Building Name**  
APPLIED TECH 200

**Abbrev**  
AT200

**Condition**  
Remodeling - C

**Fusion Room No**  
D104

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
7010-Auxiliary Classes

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
114

**Measured Area**  
110.5

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 6:49:09 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
599

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
9

**Building Name**  
APPLIED TECH 200

**Abbrev**  
AT200

**Condition**  
Remodeling - C

**Fusion Room No**  
D106

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
7010-Auxiliary Classes

**Assignable Stations**  
4

**Observed Stations**

**Assignable Area**  
994

**Measured Area**  
899

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 6:46:29 PM

# 1794 Room Assessment Data

**Id**  
600

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
9

**Building Name**  
APPLIED TECH 200

**Abbrev**  
AT200

**Condition**  
Remodeling - C

**Fusion Room No**  
D107

**ROOM NAME**

**Status**  
Active

**Use Code**  
315-Office Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
7010-Auxiliary Classes

**Assignable Stations**  
7

**Observed Stations**

**Assignable Area**  
937

**Measured Area**  
940

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 6:51:38 PM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
609

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
9

**Building Name**  
APPLIED TECH 200

**Abbrev**  
AT200

**Condition**  
Remodeling - C

**Fusion Room No**  
203N

**ROOM NAME**  
Class Lab

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0934-Electronics and Electr

**Assignable Stations**  
20

**Observed Stations**  
24

**Assignable Area**  
203

**Measured Area**  
810

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 7:07:46 PM

# 1794 Room Assessment Data

**Id**  
610

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
9

**Building Name**  
APPLIED TECH 200

**Abbrev**  
AT200

**Condition**  
Remodeling - C

**Fusion Room No**  
204

**ROOM NAME**

**Status**  
Active

**Use Code**  
110-Classroom

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
24

**Observed Stations**  
30

**Assignable Area**  
597

**Measured Area**  
908.3

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 7:09:49 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
617

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
9

**Building Name**  
APPLIED TECH 200

**Abbrev**  
AT200

**Condition**  
Remodeling - C

**Fusion Room No**  
207C

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0948-Automotive Technolo

**Assignable Stations**  
15

**Observed Stations**

**Assignable Area**  
683

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**

**Floor Condition**

**Ceiling Finish**

**Ceiling Condition**

**Wall Finish**

**Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Was not able to access room

**Fusion Recommendation**

**Review Date**  
8/10/2018 7:26:29 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
633

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
10

**Building Name**  
APPLIED TECH 300

**Abbrev**  
AT300

**Condition**  
Remodeling - C

**Fusion Room No**  
302B

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0953-Drafting Technology

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
122

**Measured Area**  
118.45

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 12:16:33 PM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
637

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
10

**Building Name**  
APPLIED TECH 300

**Abbrev**  
AT300

**Condition**  
Remodeling - C

**Fusion Room No**  
303C

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0934-Electronics and Electr

**Assignable Stations**  
20

**Observed Stations**

**Assignable Area**  
823

**Measured Area**  
771.65

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 11:47:38 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
641

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
10

**Building Name**  
APPLIED TECH 300

**Abbrev**  
AT300

**Condition**  
Remodeling - C

**Fusion Room No**  
303G

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0934-Electronics and Electr

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
103

**Measured Area**  
101.75

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 11:56:49 AM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
644

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
10

**Building Name**  
APPLIED TECH 300

**Abbrev**  
AT300

**Condition**  
Remodeling - C

**Fusion Room No**  
303M

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0934-Electronics and Electr

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
103

**Measured Area**  
104.5

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 11:57:03 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
647

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
10

**Building Name**  
APPLIED TECH 300

**Abbrev**  
AT300

**Condition**  
Remodeling - C

**Fusion Room No**  
305A

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0934-Electronics and Electr

**Assignable Stations**  
15

**Observed Stations**  
24

**Assignable Area**  
729

**Measured Area**  
728.5

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 11:33:25 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
650

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
10

**Building Name**  
APPLIED TECH 300

**Abbrev**  
AT300

**Condition**  
Remodeling - C

**Fusion Room No**  
306

**ROOM NAME**  
Custodial Storage

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
767

**Measured Area**  
756.25

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 11:27:35 AM

# 1794 Room Assessment Data

**Id**  
651

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
10

**Building Name**  
APPLIED TECH 300

**Abbrev**  
AT300

**Condition**  
Remodeling - C

**Fusion Room No**  
307

**ROOM NAME**  
Men's Restroom

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
189

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Tile

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 11:59:46 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
656

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
11

**Building Name**  
APPLIED TECH 400

**Abbrev**  
AT400

**Condition**  
Remodeling - B

**Fusion Room No**  
400B

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1030-Graphic Arts and Desi

**Assignable Stations**  
20

**Observed Stations**  
24

**Assignable Area**  
738

**Measured Area**  
754

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 10:20:05 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
677

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
11

**Building Name**  
APPLIED TECH 400

**Abbrev**  
AT400

**Condition**  
Remodeling - B

**Fusion Room No**  
404

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1011-Photography

**Assignable Stations**  
12

**Observed Stations**  
37

**Assignable Area**  
752

**Measured Area**  
759

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Desks

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/8/2018 11:09:31 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
693

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
12

**Building Name**  
APPLIED TECH 500

**Abbrev**  
AT500

**Condition**  
Remodeling - B

**Fusion Room No**  
5002

**ROOM NAME**  
Production/Print/Duplication

**Status**  
Active

**Use Code**  
720-Shop

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6770-Logistical Services

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
1121

**Measured Area**  
729

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
Exposed Structure

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 10:26:18 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
697

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
12

**Building Name**  
APPLIED TECH 500

**Abbrev**  
AT500

**Condition**  
Remodeling - B

**Fusion Room No**  
500C

**ROOM NAME**  
Building Services Office

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
See notes

**TOP/CSS Code**  
6530-Custodial Services

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
102

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This room is a telecom room

**Fusion Recommendation**  
Reclassify Room715-DP/Computer Service

**Review Date**  
9/3/2018 10:17:53 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
702

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
12

**Building Name**  
APPLIED TECH 500

**Abbrev**  
AT500

**Condition**  
Remodeling - B

**Fusion Room No**  
501A

**ROOM NAME**  
Office - Production

**Status**  
Active

**Use Code**  
730-Storage

**Use Observed**  
See notes

**TOP/CSS Code**  
6770-Logistical Services

**Assignable Stations**  
2

**Observed Stations**  
1

**Assignable Area**  
133

**Measured Area**  
101.7

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This room is and office not storage

**Fusion Recommendation**  
Reclassify Room to 310 Office

**Review Date**  
9/3/2018 10:02:22 AM

# 1794 Room Assessment Data

**Id**  
703

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
12

**Building Name**  
APPLIED TECH 500

**Abbrev**  
AT500

**Condition**  
Remodeling - B

**Fusion Room No**  
501B

**ROOM NAME**  
Office

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0956-Manufacturing and In

**Assignable Stations**  
2

**Observed Stations**

**Assignable Area**  
50

**Measured Area**  
256.69

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This room is a telecom room

**Fusion Recommendation**

**Review Date**  
9/3/2018 10:20:55 AM

# 1794 Room Assessment Data

**Id**  
704

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
12

**Building Name**  
APPLIED TECH 500

**Abbrev**  
AT500

**Condition**  
Remodeling - B

**Fusion Room No**  
501C

**ROOM NAME**  
Cross Connect Room (IDF)

**Status**  
Active

**Use Code**  
710-Data Processing/Comp

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6780-Management Inform

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
258

**Measured Area**  
108.48

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 10:19:59 AM

# 1794 Room Assessment Data

**Id**  
705

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
12

**Building Name**  
APPLIED TECH 500

**Abbrev**  
AT500

**Condition**  
Remodeling - B

**Fusion Room No**  
501D

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
See notes

**TOP/CSS Code**  
0956-Manufacturing and In

**Assignable Stations**  
5

**Observed Stations**

**Assignable Area**  
256

**Measured Area**  
256.5

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This room is an office not lab service

**Fusion Recommendation**  
Reclassify Room to 310 Office

**Review Date**  
9/3/2018 10:04:10 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
708

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
12

**Building Name**  
APPLIED TECH 500

**Abbrev**  
AT500

**Condition**  
Remodeling - B

**Fusion Room No**  
502B

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0956-Manufacturing and In

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
144

**Measured Area**  
142.5

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**

**Floor Condition**

**Ceiling Finish**

**Ceiling Condition**

**Wall Finish**

**Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Keys did not open room

**Fusion Recommendation**

**Review Date**  
9/3/2018 9:57:25 AM

# 1794 Room Assessment Data

**Id**  
709

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
12

**Building Name**  
APPLIED TECH 500

**Abbrev**  
AT500

**Condition**  
Remodeling - B

**Fusion Room No**  
502C

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0956-Manufacturing and In

**Assignable Stations**  
2

**Observed Stations**  
3

**Assignable Area**  
211

**Measured Area**  
212.8

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 9:55:14 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
717

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
13

**Building Name**  
APPLIED TECH 600

**Abbrev**  
AT600

**Condition**  
Remodeling - B

**Fusion Room No**  
601

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0948-Automotive Technolo

**Assignable Stations**  
28

**Observed Stations**  
36

**Assignable Area**  
558

**Measured Area**  
552

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Desks

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 9:26:46 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
719

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
13

**Building Name**  
APPLIED TECH 600

**Abbrev**  
AT600

**Condition**  
Remodeling - B

**Fusion Room No**  
606

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0948-Automotive Technolo

**Assignable Stations**  
1

**Observed Stations**  
2

**Assignable Area**  
159

**Measured Area**  
156.8

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 9:38:48 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  **Unassigned areas were not required to be measured**

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
728

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
14

**Building Name**  
CAFETERIA

**Abbrev**  
CAFE

**Condition**  
Remodeling - C

**Fusion Room No**  
1A

**ROOM NAME**

**Status**  
Active

**Use Code**  
655-Lounge Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6999-Other Ancillary Servic

**Assignable Stations**  
2

**Observed Stations**

**Assignable Area**  
157

**Measured Area**  
119.7

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 4:56:24 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
731

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
14

**Building Name**  
CAFETERIA

**Abbrev**  
CAFE

**Condition**  
Remodeling - C

**Fusion Room No**  
1D

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6999-Other Ancillary Servic

**Assignable Stations**  
2

**Observed Stations**

**Assignable Area**  
165

**Measured Area**  
171

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Tackboard

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 5:11:13 PM

# 1794 Room Assessment Data

**Id**  
732

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
14

**Building Name**  
CAFETERIA

**Abbrev**  
CAFE

**Condition**  
Remodeling - C

**Fusion Room No**  
1E

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6999-Other Ancillary Servic

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
78

**Measured Area**  
79.1

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 4:57:51 PM

# 1794 Room Assessment Data

**Id**  
733

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
14

**Building Name**  
CAFETERIA

**Abbrev**  
CAFE

**Condition**  
Remodeling - C

**Fusion Room No**  
1F

**ROOM NAME**  
Break Room

**Status**  
Active

**Use Code**  
655-Lounge Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6999-Other Ancillary Servic

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
270

**Measured Area**  
147.6

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
5

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 5:01:39 PM



# 1794 Room Assessment Data

**Id**  
734

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
14

**Building Name**  
CAFETERIA

**Abbrev**  
CAFE

**Condition**  
Remodeling - C

**Fusion Room No**  
P1

**ROOM NAME**  
Mech

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Exposed Structure

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 4:17:47 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
736

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
14

**Building Name**  
CAFETERIA

**Abbrev**  
CAFE

**Condition**  
Remodeling - C

**Fusion Room No**  
1H

**ROOM NAME**

**Status**  
Active

**Use Code**  
680-Meeting Room

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6999-Other Ancillary Servic

**Assignable Stations**  
44

**Observed Stations**  
46

**Assignable Area**  
649

**Measured Area**  
651.2

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 5:06:41 PM

# 1794 Room Assessment Data

**Id**  
737

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
14

**Building Name**  
CAFETERIA

**Abbrev**  
CAFE

**Condition**  
Remodeling - C

**Fusion Room No**  
P2B

**ROOM NAME**  
Mech

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Exposed Structure

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 5:24:17 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
740

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
14

**Building Name**  
CAFETERIA

**Abbrev**  
CAFE

**Condition**  
Remodeling - C

**Fusion Room No**  
B2

**ROOM NAME**  
Mechanical Room

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Exposed Structure

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 4:17:47 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
742

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
14

**Building Name**  
CAFETERIA

**Abbrev**  
CAFE

**Condition**  
Remodeling - C

**Fusion Room No**  
3

**ROOM NAME**

**Status**  
Active

**Use Code**  
635-Food Facilities Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6940-Food Services

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
2216

**Measured Area**  
685.72

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 4:49:22 PM

# 1794 Room Assessment Data

**Id**  
743

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
14

**Building Name**  
CAFETERIA

**Abbrev**  
CAFE

**Condition**  
Remodeling - C

**Fusion Room No**  
4

**ROOM NAME**

**Status**  
Active

**Use Code**  
630-Food Facilities

**Use Observed**  
Unassigned

**TOP/CSS Code**  
6940-Food Services

**Assignable Stations**  
13

**Observed Stations**

**Assignable Area**  
2585

**Measured Area**  
1690.9

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Tile

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 4:38:44 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
746

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
14

**Building Name**  
CAFETERIA

**Abbrev**  
CAFE

**Condition**  
Remodeling - C

**Fusion Room No**  
6

**ROOM NAME**

**Status**  
Active

**Use Code**  
670-Recreation

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6999-Other Ancillary Servic

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
925

**Measured Area**  
2006.79

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Room six is the serving area

**Fusion Recommendation**

**Review Date**  
7/20/2018 4:36:57 PM

# 1794 Room Assessment Data

**Id**  
747

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
14

**Building Name**  
CAFETERIA

**Abbrev**  
CAFE

**Condition**  
Remodeling - C

**Fusion Room No**  
7

**ROOM NAME**  
Student Recreation/Pool Room

**Status**  
Active

**Use Code**  
670-Recreation

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6999-Other Ancillary Servic

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
910

**Measured Area**  
880

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
Exposed Structure

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 5:23:54 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
753

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
14

**Building Name**  
CAFETERIA

**Abbrev**  
CAFE

**Condition**  
Remodeling - C

**Fusion Room No**  
13

**ROOM NAME**  
Janitor

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
4

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 5:03:27 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
764

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
14

**Building Name**  
CAFETERIA

**Abbrev**  
CAFE

**Condition**  
Remodeling - C

**Fusion Room No**  
26

**ROOM NAME**  
Mech - Chiller

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Exposed Structure

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/20/2018 5:13:31 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
767

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
17

**Building Name**  
FACULTY OFFICE A

**Abbrev**  
OFF A

**Condition**  
Remodeling - C

**Fusion Room No**  
A1

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1501-English

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
80

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/2/2018 6:55:44 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
772

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
17

**Building Name**  
FACULTY OFFICE A

**Abbrev**  
OFF A

**Condition**  
Remodeling - C

**Fusion Room No**  
A6

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1501-English

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
80

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/2/2018 7:32:46 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
777

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
17

**Building Name**  
FACULTY OFFICE A

**Abbrev**  
OFF A

**Condition**  
Remodeling - C

**Fusion Room No**  
A11

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1501-English

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
80

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/2/2018 7:04:32 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
793

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
17

**Building Name**  
FACULTY OFFICE A

**Abbrev**  
OFF A

**Condition**  
Remodeling - C

**Fusion Room No**  
C27

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1101-Foreign Languages, G

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
80

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/2/2018 6:46:48 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id: 795    Campus Name: Fresno City College    Campus Code: 571

Build No: 17    Building Name: FACULTY OFFICE A    Abbrev: OFF A    Condition: Remodeling - C

Fusion Room No: C29    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 1509-Philosophy

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 80    Measured Area: 80    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Carpet    Floor Condition: 4

Ceiling Finish: ACT    Ceiling Condition: 2

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 8/2/2018 6:29:22 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
798

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
17

**Building Name**  
FACULTY OFFICE A

**Abbrev**  
OFF A

**Condition**  
Remodeling - C

**Fusion Room No**  
C32

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1506-Speech Communicati

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
80

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/2/2018 6:46:17 PM



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id: 800    Campus Name: Fresno City College    Campus Code: 571

Build No: 17    Building Name: FACULTY OFFICE A    Abbrev: OFF A    Condition: Remodeling - C

Fusion Room No: C34    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 1506-Speech Communicati

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 80    Measured Area: 80    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Carpet    Floor Condition: 2

Ceiling Finish: ACT    Ceiling Condition: 2

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 8/2/2018 6:44:46 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
808

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
17

**Building Name**  
FACULTY OFFICE A

**Abbrev**  
OFF A

**Condition**  
Remodeling - C

**Fusion Room No**  
D41A

**ROOM NAME**

**Status**  
Active

**Use Code**  
680-Meeting Room

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
8

**Observed Stations**  
11

**Assignable Area**  
150

**Measured Area**  
149.5

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/2/2018 7:46:05 PM

# 1794 Room Assessment Data

**Id**  
809

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
17

**Building Name**  
FACULTY OFFICE A

**Abbrev**  
OFF A

**Condition**  
Remodeling - C

**Fusion Room No**  
D41B

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6010-Academic Administra

**Assignable Stations**  
1

**Observed Stations**  
2

**Assignable Area**  
188

**Measured Area**  
189

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/2/2018 7:44:10 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id **817** Campus Name **Fresno City College** Campus Code **571**

Build No **19** Building Name **SCIENCE** Abbrev **SCI** Condition **Remodeling - C**

Fusion Room No **1** ROOM NAME  Status **Active**

Use Code **310-Office** Use Observed **Matches Fusion** TOP/CSS Code **0099-General Assignment**

Assignable Stations **1** Observed Stations **1**

Assignable Area **81** Measured Area **79.06** Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish **Carpet** Floor Condition **3**

Ceiling Finish **ACT** Ceiling Condition **2**

Wall Finish **Tackboard** Wall Condition **2**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date **8/7/2018 7:39:37 AM**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
819

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
3

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
81

**Measured Area**  
79.06

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 7:42:14 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
822

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
6

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
81

**Measured Area**  
79.8

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 7:47:36 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
831

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
15

**ROOM NAME**  
Faculty Office

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**

**Observed Stations**  
1

**Assignable Area**  
85

**Measured Area**  
85.32

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 8:02:52 AM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
843

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
50A

**ROOM NAME**  
Corridor

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
279

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 8:20:09 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  **Unassigned areas were not required to be measured**

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
849

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
54

**ROOM NAME**  
Work Room

**Status**  
Active

**Use Code**  
315-Office Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6010-Academic Administra

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
177

**Measured Area**  
180

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Tackboard

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 8:32:08 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
855

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
65

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
2

**Observed Stations**  
2

**Assignable Area**  
148

**Measured Area**  
149

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 8:39:47 AM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
862

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
70

**ROOM NAME**

**Status**  
Active

**Use Code**  
110-Classroom

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
90

**Observed Stations**  
95

**Assignable Area**  
1257

**Measured Area**  
1248.45

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Chairs-fixed

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 8:48:37 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
867

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
101

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0401-Biology, General

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
81

**Measured Area**  
79.2

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 9:00:18 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
871

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
105

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0401-Biology, General

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
81

**Measured Area**  
80.4

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 9:06:59 AM



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
876

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
110

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0401-Biology, General

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
81

**Measured Area**  
79.2

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 9:11:07 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
892

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
150

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0401-Biology, General

**Assignable Stations**  
30

**Observed Stations**  
32

**Assignable Area**  
1078

**Measured Area**  
1044

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 9:39:43 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
897

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
155

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0401-Biology, General

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
1962

**Measured Area**  
1958

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 9:28:36 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
899

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
160

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0401-Biology, General

**Assignable Stations**  
30

**Observed Stations**  
32

**Assignable Area**  
1078

**Measured Area**  
1073

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 9:46:19 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  
904

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
177

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0401-Biology, General

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
364

**Measured Area**  
356.4

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 9:52:22 AM

# 1794 Room Assessment Data

**Id**  
905

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
180

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0401-Biology, General

**Assignable Stations**  
24

**Observed Stations**  
24

**Assignable Area**  
947

**Measured Area**  
957

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 9:53:58 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
907

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
195

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0401-Biology, General

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
88

**Measured Area**  
87.15

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 9:57:13 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
909

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
200C

**ROOM NAME**  
Outside Hall

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 10:01:30 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
915

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
200B

**ROOM NAME**  
Outside Hall

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 10:07:57 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
927

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
211

**ROOM NAME**  
Data Cross connect

**Status**  
Active

**Use Code**  
715-DP/Computer Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6780-Management Inform

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
157

**Measured Area**  
153.4

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 10:21:06 AM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
935

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
220

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1905-Chemistry, General

**Assignable Stations**  
30

**Observed Stations**  
32

**Assignable Area**  
1078

**Measured Area**  
1073

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 11:08:52 AM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
937

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
227

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1905-Chemistry, General

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
71

**Measured Area**  
91.8

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 11:05:01 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
942

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
250

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1905-Chemistry, General

**Assignable Stations**  
30

**Observed Stations**  
32

**Assignable Area**  
1078

**Measured Area**  
1073

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Desks

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 11:01:20 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
944

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
255

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1901-Physical Sciences, Ge

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
1080

**Measured Area**  
946

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 10:30:18 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
949

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
260

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1902-Physics, General

**Assignable Stations**  
30

**Observed Stations**  
40

**Assignable Area**  
1078

**Measured Area**  
1073

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 10:56:19 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
951

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
275

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
See notes

**TOP/CSS Code**  
1901-Physical Sciences, Ge

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
335

**Measured Area**  
336

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This room is Office not lab service

**Fusion Recommendation**  
Reclassify Room to 310 Office

**Review Date**  
8/7/2018 10:38:40 AM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
953

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
19

**Building Name**  
SCIENCE

**Abbrev**  
SCI

**Condition**  
Remodeling - C

**Fusion Room No**  
280A

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1901-Physical Sciences, Ge

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
146

**Measured Area**  
140

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 10:48:13 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
958

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
20

**Building Name**  
ANIMAL HOUSE

**Abbrev**  
AHOUSE

**Condition**  
Remodeling - A

**Fusion Room No**  
2

**ROOM NAME**  
Storage

**Status**  
Active

**Use Code**  
730-Storage

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0401-Biology, General

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
45

**Measured Area**  
42

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Exposed Structure

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 11:26:16 AM

# 1794 Room Assessment Data

**Id**  
960

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
21

**Building Name**  
GREENHOUSE PREP

**Abbrev**  
GRPREP

**Condition**  
Remodeling - B

**Fusion Room No**  
1

**ROOM NAME**

**Status**  
Active

**Use Code**  
585-Greenhouse Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0401-Biology, General

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
439

**Measured Area**  
399

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 11:25:30 AM

# 1794 Room Assessment Data

**Id**  
962

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
22

**Building Name**  
GREENHOUSE

**Abbrev**  
GHOUSE

**Condition**  
Remodeling - C

**Fusion Room No**  
1

**ROOM NAME**

**Status**  
Active

**Use Code**  
580-Greenhouse

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0401-Biology, General

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
843

**Measured Area**  
850

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**

**Ceiling Finish**

**Ceiling Condition**

**Wall Finish**

**Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/7/2018 11:26:58 AM



# 1794 Room Assessment Data

**Id**  
964

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
101

**ROOM NAME**

**Status**  
Active

**Use Code**  
230-Individual Study Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**  
8

**Observed Stations**

**Assignable Area**  
341

**Measured Area**  
342.2

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 3:07:21 PM

# 1794 Room Assessment Data

**Id**  
965

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
102

**ROOM NAME**

**Status**  
Active

**Use Code**  
230-Individual Study Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**  
8

**Observed Stations**

**Assignable Area**  
341

**Measured Area**  
342.2

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 3:55:45 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
967

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
104

**ROOM NAME**

**Status**  
Active

**Use Code**  
110-Classroom

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
47

**Observed Stations**  
43

**Assignable Area**  
693

**Measured Area**  
696.78

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Desks

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 3:13:22 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
969

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
106

**ROOM NAME**

**Status**  
Active

**Use Code**  
230-Individual Study Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
71

**Measured Area**  
72

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 3:26:08 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  
972

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
109

**ROOM NAME**

**Status**  
Active

**Use Code**  
230-Individual Study Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
71

**Measured Area**  
72

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 3:56:05 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
974

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
112

**ROOM NAME**

**Status**  
Active

**Use Code**  
230-Individual Study Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
142

**Measured Area**  
117

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Tackboard

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 3:20:54 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
976

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
114

**ROOM NAME**

**Status**  
Active

**Use Code**  
230-Individual Study Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
71

**Measured Area**  
72

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 3:29:34 PM

# 1794 Room Assessment Data

**Id**  
977

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
115

**ROOM NAME**

**Status**  
Active

**Use Code**  
230-Individual Study Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
71

**Measured Area**  
72

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 3:30:04 PM

# 1794 Room Assessment Data

**Id**  
978

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
116

**ROOM NAME**

**Status**  
Active

**Use Code**  
230-Individual Study Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
71

**Measured Area**  
72

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 3:30:46 PM

# 1794 Room Assessment Data

**Id**  
979

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
117

**ROOM NAME**

**Status**  
Active

**Use Code**  
230-Individual Study Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
71

**Measured Area**  
72

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 3:31:16 PM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
983

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
121

**ROOM NAME**

**Status**  
Active

**Use Code**  
715-DP/Computer Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6780-Management Inform

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
71

**Measured Area**  
72

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 3:17:51 PM

# 1794 Room Assessment Data

**Id**  
984

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
122

**ROOM NAME**

**Status**  
Active

**Use Code**  
220-Spec Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**  
16

**Observed Stations**

**Assignable Area**  
717

**Measured Area**  
722.85

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 3:35:31 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
997

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
135

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**  
100

**Observed Stations**

**Assignable Area**  
1909

**Measured Area**  
1903.5

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Wood

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 3:58:28 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
999

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
137

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
375

**Measured Area**  
372

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
5

**Ceiling Finish**  
ACT

**Ceiling Condition**  
5

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 4:39:26 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1005

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
205

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1506-Speech Communicati

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
75

**Measured Area**  
75

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 4:17:10 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1008

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
208

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
75

**Measured Area**  
80

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 4:19:21 PM

# 1794 Room Assessment Data

**Id**  
1009

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
209

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
75

**Measured Area**  
75

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 4:19:54 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1014

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
216

**ROOM NAME**

**Status**  
Active

**Use Code**  
230-Individual Study Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1004-Music

**Assignable Stations**  
2

**Observed Stations**  
1

**Assignable Area**  
94

**Measured Area**  
96.32

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 4:24:32 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1019

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
222

**ROOM NAME**

**Status**  
Active

**Use Code**  
110-Classroom

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
35

**Observed Stations**  
30

**Assignable Area**  
561

**Measured Area**  
556.96

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Desks

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 4:35:14 PM



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1021

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
224

**ROOM NAME**  
Staff Restroom, Unisex

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Unassigned

**TOP/CSS Code**  
1004-Music

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
91

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Tile

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 4:37:29 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1025

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
23

**Building Name**  
SPEECH-MUSIC

**Abbrev**  
SP-MUS

**Condition**  
Remodeling - C

**Fusion Room No**  
228A

**ROOM NAME**  
Elec/Roof Access

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
5

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
4

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 4:41:29 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1043

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
26

**Building Name**  
LANGUAGE ARTS

**Abbrev**  
L ARTS

**Condition**  
Remodeling - C

**Fusion Room No**  
106

**ROOM NAME**

**Status**  
Active

**Use Code**  
110-Classroom

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
35

**Observed Stations**  
24

**Assignable Area**  
525

**Measured Area**  
450

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Desks

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/2/2018 5:10:42 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1047

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
26

**Building Name**  
LANGUAGE ARTS

**Abbrev**  
L ARTS

**Condition**  
Remodeling - C

**Fusion Room No**  
121

**ROOM NAME**

**Status**  
Active

**Use Code**  
230-Individual Study Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1501-English

**Assignable Stations**  
35

**Observed Stations**  
30

**Assignable Area**  
606

**Measured Area**  
600

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/2/2018 5:15:50 PM

# 1794 Room Assessment Data

**Id**  
1048

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
26

**Building Name**  
LANGUAGE ARTS

**Abbrev**  
L ARTS

**Condition**  
Remodeling - C

**Fusion Room No**  
122

**ROOM NAME**  
Writing Skills Lab

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1502-Language Arts

**Assignable Stations**  
40

**Observed Stations**  
30

**Assignable Area**  
615

**Measured Area**  
600

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/2/2018 5:17:42 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  
1053

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
26

**Building Name**  
LANGUAGE ARTS

**Abbrev**  
L ARTS

**Condition**  
Remodeling - C

**Fusion Room No**  
127

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
See notes

**TOP/CSS Code**  
4930-General Studies

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
119

**Measured Area**  
111.6

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This room is no longer in office is a telecom

**Fusion Recommendation**  
Reclassify Room715-DP/Computer Service

**Review Date**  
8/2/2018 5:23:00 PM

# 1794 Room Assessment Data

Id: 1054    Campus Name: Fresno City College    Campus Code: 571

Build No: 26    Building Name: LANGUAGE ARTS    Abbrev: L ARTS    Condition: Remodeling - C

Fusion Room No: 128    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 1501-English

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 81    Measured Area: 81    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Carpet    Floor Condition: 3

Ceiling Finish: ACT    Ceiling Condition: 2

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 8/2/2018 5:33:43 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id: 1056    Campus Name: Fresno City College    Campus Code: 571

Build No: 26    Building Name: LANGUAGE ARTS    Abbrev: L ARTS    Condition: Remodeling - C

Fusion Room No: 130    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Unassigned    TOP/CSS Code: 1501-English

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 176    Measured Area: 161.5    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Carpet    Floor Condition: 3

Ceiling Finish: ACT    Ceiling Condition: 3

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 8/2/2018 5:39:26 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1073

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
26

**Building Name**  
LANGUAGE ARTS

**Abbrev**  
L ARTS

**Condition**  
Remodeling - C

**Fusion Room No**  
207A

**ROOM NAME**  
Cross Connect

**Status**  
Active

**Use Code**  
715-DP/Computer Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6780-Management Inform

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
115

**Measured Area**  
110.5

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/2/2018 6:07:25 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1089

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
27

**Building Name**  
ART-HOME ECON

**Abbrev**  
ART-HE

**Condition**  
Remodeling - C

**Fusion Room No**  
101E

**ROOM NAME**  
Men's Restroom

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
176

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
4

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Tile

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 9:06:54 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  
1094

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
27

**Building Name**  
ART-HOME ECON

**Abbrev**  
ART-HE

**Condition**  
Remodeling - C

**Fusion Room No**  
102

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1002-Art (Painting, Drawin

**Assignable Stations**  
24

**Observed Stations**

**Assignable Area**  
1433

**Measured Area**  
1794

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Exposed Structure

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 9:13:25 AM

# 1794 Room Assessment Data

**Id**  
1095

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
27

**Building Name**  
ART-HOME ECON

**Abbrev**  
ART-HE

**Condition**  
Remodeling - C

**Fusion Room No**  
102A

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1002-Art (Painting, Drawin

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
64

**Measured Area**  
42

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 9:15:34 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1097

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
27

**Building Name**  
ART-HOME ECON

**Abbrev**  
ART-HE

**Condition**  
Remodeling - C

**Fusion Room No**  
102C

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1002-Art (Painting, Drawin

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
125

**Measured Area**  
84

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
5

**Wall Finish**  
Paint

**Wall Condition**  
4

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 9:18:14 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1109

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
27

**Building Name**  
ART-HOME ECON

**Abbrev**  
ART-HE

**Condition**  
Remodeling - C

**Fusion Room No**  
108

**ROOM NAME**

**Status**  
Active

**Use Code**  
110-Classroom

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
40

**Observed Stations**  
35

**Assignable Area**  
589

**Measured Area**  
552

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 9:39:44 AM



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1111

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
27

**Building Name**  
ART-HOME ECON

**Abbrev**  
ART-HE

**Condition**  
Remodeling - C

**Fusion Room No**  
110

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1306-Nutrition, Foods, and

**Assignable Stations**  
30

**Observed Stations**  
20

**Assignable Area**  
1240

**Measured Area**  
1260

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Tile

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 9:43:08 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1113

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
27

**Building Name**  
ART-HOME ECON

**Abbrev**  
ART-HE

**Condition**  
Remodeling - C

**Fusion Room No**  
110B

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1306-Nutrition, Foods, and

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
36

**Measured Area**  
36

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
5

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
FRP

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 9:47:04 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1124

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
27

**Building Name**  
ART-HOME ECON

**Abbrev**  
ART-HE

**Condition**  
Remodeling - C

**Fusion Room No**  
201A

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1002-Art (Painting, Drawin

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
48

**Measured Area**  
45

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 10:08:09 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1130

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
27

**Building Name**  
ART-HOME ECON

**Abbrev**  
ART-HE

**Condition**  
Remodeling - C

**Fusion Room No**  
204

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1002-Art (Painting, Drawin

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
100

**Measured Area**  
80

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 10:18:18 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1133

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
27

**Building Name**  
ART-HOME ECON

**Abbrev**  
ART-HE

**Condition**  
Remodeling - C

**Fusion Room No**  
205A

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1002-Art (Painting, Drawin

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
30

**Measured Area**  
30

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
5

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 10:22:02 AM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1138

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
27

**Building Name**  
ART-HOME ECON

**Abbrev**  
ART-HE

**Condition**  
Remodeling - C

**Fusion Room No**  
207B

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
See notes

**TOP/CSS Code**  
1002-Art (Painting, Drawin

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
80

**Measured Area**  
42

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This is not an office it is class lab service

**Fusion Recommendation**  
Reclassify Room to 215 Lab Service

**Review Date**  
8/10/2018 10:30:50 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1140

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
27

**Building Name**  
ART-HOME ECON

**Abbrev**  
ART-HE

**Condition**  
Remodeling - C

**Fusion Room No**  
207D

**ROOM NAME**  
Office

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1002-Art (Painting, Drawin

**Assignable Stations**

**Observed Stations**  
1

**Assignable Area**  
84

**Measured Area**  
83.3

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 10:33:07 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1144

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
27

**Building Name**  
ART-HOME ECON

**Abbrev**  
ART-HE

**Condition**  
Remodeling - C

**Fusion Room No**  
209

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1301-Family and Consumer

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
80

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
5

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 10:43:33 AM

# 1794 Room Assessment Data

**Id**  
1145

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
27

**Building Name**  
ART-HOME ECON

**Abbrev**  
ART-HE

**Condition**  
Remodeling - C

**Fusion Room No**  
210

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1301-Family and Consumer

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
80

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 10:43:33 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1148

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
27

**Building Name**  
ART-HOME ECON

**Abbrev**  
ART-HE

**Condition**  
Remodeling - C

**Fusion Room No**  
211B

**ROOM NAME**

**Status**  
Active

**Use Code**  
215-Class Lab Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1301-Family and Consumer

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
146

**Measured Area**  
145.2

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 10:45:50 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  **Unassigned areas were not required to be measured**

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1204

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
28

**Building Name**  
THEATER ARTS

**Abbrev**  
T ARTS

**Condition**  
Remodeling - B

**Fusion Room No**  
121A

**ROOM NAME**  
Stage Hall

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
371

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**

**Floor Condition**

**Ceiling Finish**

**Ceiling Condition**

**Wall Finish**

**Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Room not on plans ok unassigned

**Fusion Recommendation**

**Review Date**  
8/10/2018 6:15:12 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1211

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
28

**Building Name**  
THEATER ARTS

**Abbrev**  
T ARTS

**Condition**  
Remodeling - B

**Fusion Room No**  
204

**ROOM NAME**

**Status**  
Active

**Use Code**  
615-Assembly Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1007-Dramatic Arts

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
140

**Measured Area**  
150.29

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 6:29:49 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1214

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
28

**Building Name**  
THEATER ARTS

**Abbrev**  
T ARTS

**Condition**  
Remodeling - B

**Fusion Room No**  
208A

**ROOM NAME**  
Janitor

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 6:21:05 PM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id: 1219    Campus Name: Fresno City College    Campus Code: 571

Build No: 29    Building Name: BUSINESS EDUCATION    Abbrev: BUS ED    Condition: Remodeling - B

Fusion Room No: 102    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 0509-Marketing and Distrib

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 80    Measured Area: 80    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Carpet    Floor Condition: 3

Ceiling Finish: ACT    Ceiling Condition: 3

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/31/2018 6:48:56 PM

# 1794 Room Assessment Data

Id: 1220    Campus Name: Fresno City College    Campus Code: 571

Build No: 29    Building Name: BUSINESS EDUCATION    Abbrev: BUS ED    Condition: Remodeling - B

Fusion Room No: 103    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 0506-Business Management

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 80    Measured Area: 80    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Carpet    Floor Condition: 3

Ceiling Finish: ACT    Ceiling Condition: 3

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/31/2018 6:48:56 PM

# 1794 Room Assessment Data

**Id**  
1221

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
29

**Building Name**  
BUSINESS EDUCATION

**Abbrev**  
BUS ED

**Condition**  
Remodeling - B

**Fusion Room No**  
104

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0934-Electronics and Electr

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
80

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 6:48:56 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id: 1223    Campus Name: Fresno City College    Campus Code: 571

Build No: 29    Building Name: BUSINESS EDUCATION    Abbrev: BUS ED    Condition: Remodeling - B

Fusion Room No: 106    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 0506-Business Management

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 80    Measured Area: 80    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Carpet    Floor Condition: 3

Ceiling Finish: ACT    Ceiling Condition: 3

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/31/2018 6:48:56 PM



# 1794 Room Assessment Data

**Id**  
1224

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
29

**Building Name**  
BUSINESS EDUCATION

**Abbrev**  
BUS ED

**Condition**  
Remodeling - B

**Fusion Room No**  
107

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0509-Marketing and Distrib

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
80

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 6:48:56 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1226

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
29

**Building Name**  
BUSINESS EDUCATION

**Abbrev**  
BUS ED

**Condition**  
Remodeling - B

**Fusion Room No**  
109

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0501-Business and Comme

**Assignable Stations**  
2

**Observed Stations**  
1

**Assignable Area**  
149

**Measured Area**  
149.5

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 6:48:56 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id: 1228    Campus Name: Fresno City College    Campus Code: 571

Build No: 29    Building Name: BUSINESS EDUCATION    Abbrev: BUS ED    Condition: Remodeling - B

Fusion Room No: 110A    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Unassigned    TOP/CSS Code: 0514-Office Technology/Of

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 168    Measured Area: 169.06    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Carpet    Floor Condition: 2

Ceiling Finish: ACT    Ceiling Condition: 3

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/31/2018 6:48:56 PM

# 1794 Room Assessment Data

Id: 1229    Campus Name: Fresno City College    Campus Code: 571

Build No: 29    Building Name: BUSINESS EDUCATION    Abbrev: BUS ED    Condition: Remodeling - B

Fusion Room No: 110B    ROOM NAME:    Status: Active

Use Code: 315-Office Service    Use Observed: Matches Fusion    TOP/CSS Code: 0514-Office Technology/Of

Assignable Stations:    Observed Stations:

Assignable Area: 72    Measured Area: 72    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: VCT    Floor Condition: 2

Ceiling Finish: ACT    Ceiling Condition: 3

Wall Finish: Paint    Wall Condition: 3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/31/2018 6:48:56 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id: 1239    Campus Name: Fresno City College    Campus Code: 571

Build No: 29    Building Name: BUSINESS EDUCATION    Abbrev: BUS ED    Condition: Remodeling - B

Fusion Room No: 118    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 0502-Accounting

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 80    Measured Area: 70    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Carpet    Floor Condition: 3

Ceiling Finish: ACT    Ceiling Condition: 3

Wall Finish: Wood    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/31/2018 6:48:56 PM



# 1794 Room Assessment Data

**Id**  
1240

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
29

**Building Name**  
BUSINESS EDUCATION

**Abbrev**  
BUS ED

**Condition**  
Remodeling - B

**Fusion Room No**  
119

**ROOM NAME**  
Elec/Fire Alarm panel

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 6:49:50 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1244

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
29

**Building Name**  
BUSINESS EDUCATION

**Abbrev**  
BUS ED

**Condition**  
Remodeling - B

**Fusion Room No**  
123

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0701-Information Technolo

**Assignable Stations**  
35

**Observed Stations**  
25

**Assignable Area**  
733

**Measured Area**  
741

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 6:15:28 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id: 1246    Campus Name: Fresno City College    Campus Code: 571

Build No: 29    Building Name: BUSINESS EDUCATION    Abbrev: BUS ED    Condition: Remodeling - B

Fusion Room No: 125    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 0701-Information Technolo

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 80    Measured Area: 79.18    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Carpet    Floor Condition: 2

Ceiling Finish: ACT    Ceiling Condition: 2

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/31/2018 6:25:59 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
1248

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
29

**Building Name**  
BUSINESS EDUCATION

**Abbrev**  
BUS ED

**Condition**  
Remodeling - B

**Fusion Room No**  
127A

**ROOM NAME**  
Corridor

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
997

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 6:05:42 PM

# 1794 Room Assessment Data

**Id**  
1249

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
29

**Building Name**  
BUSINESS EDUCATION

**Abbrev**  
BUS ED

**Condition**  
Remodeling - B

**Fusion Room No**  
127

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0701-Information Technolo

**Assignable Stations**  
30

**Observed Stations**  
33

**Assignable Area**  
993

**Measured Area**  
1008

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 6:10:34 PM

# 1794 Room Assessment Data

**Id**  
1250

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
29

**Building Name**  
BUSINESS EDUCATION

**Abbrev**  
BUS ED

**Condition**  
Remodeling - B

**Fusion Room No**  
128

**ROOM NAME**  
Office

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0509-Marketing and Distrib

**Assignable Stations**

**Observed Stations**  
1

**Assignable Area**  
189

**Measured Area**  
185

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 6:02:09 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1253

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
29

**Building Name**  
BUSINESS EDUCATION

**Abbrev**  
BUS ED

**Condition**  
Remodeling - B

**Fusion Room No**  
128C

**ROOM NAME**  
Display Case

**Status**  
Active

**Use Code**  
620-Exhibition

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0509-Marketing and Distrib

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
128

**Measured Area**  
45

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**

**Ceiling Finish**

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 6:04:12 PM

# 1794 Room Assessment Data

**Id**  
1254

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
29

**Building Name**  
BUSINESS EDUCATION

**Abbrev**  
BUS ED

**Condition**  
Remodeling - B

**Fusion Room No**  
129

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0701-Information Technolo

**Assignable Stations**  
28

**Observed Stations**  
27

**Assignable Area**  
733

**Measured Area**  
755.25

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 5:57:34 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
1256

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
29

**Building Name**  
BUSINESS EDUCATION

**Abbrev**  
BUS ED

**Condition**  
Remodeling - B

**Fusion Room No**  
131

**ROOM NAME**

**Status**  
Active

**Use Code**  
110-Classroom

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
44

**Observed Stations**  
32

**Assignable Area**  
886

**Measured Area**  
883.5

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 5:52:18 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1260

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
29

**Building Name**  
BUSINESS EDUCATION

**Abbrev**  
BUS ED

**Condition**  
Remodeling - B

**Fusion Room No**  
134

**ROOM NAME**

**Status**  
Active

**Use Code**  
110-Classroom

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
36

**Observed Stations**  
46

**Assignable Area**  
866

**Measured Area**  
806

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Desks

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 5:41:54 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id: 1269    Campus Name: Fresno City College    Campus Code: 571

Build No: 29    Building Name: BUSINESS EDUCATION    Abbrev: BUS ED    Condition: Remodeling - B

Fusion Room No: 202    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 0514-Office Technology/Of

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 82    Measured Area: 82.5    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Carpet    Floor Condition: 3

Ceiling Finish: ACT    Ceiling Condition: 3

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/31/2018 6:54:48 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id: 1279    Campus Name: Fresno City College    Campus Code: 571

Build No: 29    Building Name: BUSINESS EDUCATION    Abbrev: BUS ED    Condition: Remodeling - B

Fusion Room No: 211    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 0502-Accounting

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 82    Measured Area: 82.5    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Carpet    Floor Condition: 3

Ceiling Finish: ACT    Ceiling Condition: 3

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/31/2018 6:59:50 PM



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1284

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
29

**Building Name**  
BUSINESS EDUCATION

**Abbrev**  
BUS ED

**Condition**  
Remodeling - B

**Fusion Room No**  
214

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0514-Office Technology/Of

**Assignable Stations**  
20

**Observed Stations**  
25

**Assignable Area**  
507

**Measured Area**  
545.3

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 7:11:01 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
1288

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
29

**Building Name**  
BUSINESS EDUCATION

**Abbrev**  
BUS ED

**Condition**  
Remodeling - B

**Fusion Room No**  
218

**ROOM NAME**

**Status**  
Active

**Use Code**  
210-Class Lab

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0514-Office Technology/Of

**Assignable Stations**  
35

**Observed Stations**  
26

**Assignable Area**  
768

**Measured Area**  
735.8

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/31/2018 7:19:11 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1306

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
30

**Building Name**  
BUILDING A

**Abbrev**  
A

**Condition**  
Remodeling - C

**Fusion Room No**  
100J

**ROOM NAME**  
Office Hall

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
176

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/15/2018 11:50:10 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1310

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
30

**Building Name**  
BUILDING A

**Abbrev**  
A

**Condition**  
Remodeling - C

**Fusion Room No**  
101

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6420-Disabled Students Pr

**Assignable Stations**  
2

**Observed Stations**  
2

**Assignable Area**  
256

**Measured Area**  
259.26

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 2:34:18 PM

# 1794 Room Assessment Data

**Id**  
1311

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
30

**Building Name**  
BUILDING A

**Abbrev**  
A

**Condition**  
Remodeling - C

**Fusion Room No**  
101A

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
See notes

**TOP/CSS Code**  
6420-Disabled Students Pr

**Assignable Stations**  
1

**Observed Stations**  
3

**Assignable Area**  
87

**Measured Area**  
85.14

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Room is a testing room not in office

**Fusion Recommendation**  
Reclassify Room to 410 Read-Study Room

**Review Date**  
6/15/2018 11:50:10 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id **1313** Campus Name **Fresno City College** Campus Code **571**

Build No **30** Building Name **BUILDING A** Abbrev **A** Condition **Remodeling - C**

Fusion Room No **101C** ROOM NAME  Status **Active**

Use Code **310-Office** Use Observed **See notes** TOP/CSS Code **6420-Disabled Students Pr**

Assignable Stations **1** Observed Stations **9**

Assignable Area **190** Measured Area **183.68** Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish **Carpet** Floor Condition **1**

Ceiling Finish **ACT** Ceiling Condition **2**

Wall Finish **Paint** Wall Condition **1**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment **Who appears to be testing room not office**

Fusion Recommendation **Reclassify Room to 410 Read-Study Room**

Review Date **6/15/2018 11:50:10 AM**

# 1794 Room Assessment Data

**Id**  
1314

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
30

**Building Name**  
BUILDING A

**Abbrev**  
A

**Condition**  
Remodeling - C

**Fusion Room No**  
101D

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
See notes

**TOP/CSS Code**  
6420-Disabled Students Pr

**Assignable Stations**  
1

**Observed Stations**  
6

**Assignable Area**  
149

**Measured Area**  
134.16

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Room appears to be testing room not in office

**Fusion Recommendation**  
Reclassify Room to 410 Read-Study Room

**Review Date**  
8/10/2018 2:35:08 PM

# 1794 Room Assessment Data

**Id**  
1315

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
30

**Building Name**  
BUILDING A

**Abbrev**  
A

**Condition**  
Remodeling - C

**Fusion Room No**  
101E

**ROOM NAME**

**Status**  
Active

**Use Code**  
680-Meeting Room

**Use Observed**  
See notes

**TOP/CSS Code**  
6420-Disabled Students Pr

**Assignable Stations**  
6

**Observed Stations**  
1

**Assignable Area**  
188

**Measured Area**  
182

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This room is an Office

**Fusion Recommendation**  
Reclassify Room to 310 Office

**Review Date**  
8/10/2018 2:36:55 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1320

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
30

**Building Name**  
BUILDING A

**Abbrev**  
A

**Condition**  
Remodeling - C

**Fusion Room No**  
102A

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6420-Disabled Students Pr

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
157

**Measured Area**  
155.38

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**  
Desks

**Floor Finish**  
VCT

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/15/2018 11:50:10 AM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1322

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
30

**Building Name**  
BUILDING A

**Abbrev**  
A

**Condition**  
Remodeling - C

**Fusion Room No**  
102C

**ROOM NAME**  
Meeting/Workroom

**Status**  
Active

**Use Code**  
680-Meeting Room

**Use Observed**  
See notes

**TOP/CSS Code**  
6420-Disabled Students Pr

**Assignable Stations**  
2

**Observed Stations**

**Assignable Area**  
82

**Measured Area**  
79.73

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Room is a workroom office work not meeting room

**Fusion Recommendation**  
Reclassify to 315 Office Service

**Review Date**  
6/15/2018 11:50:10 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1324

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
30

**Building Name**  
BUILDING A

**Abbrev**  
A

**Condition**  
Remodeling - C

**Fusion Room No**  
103A

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Unassigned

**TOP/CSS Code**  
6420-Disabled Students Pr

**Assignable Stations**  
3

**Observed Stations**

**Assignable Area**  
190

**Measured Area**  
189.93

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/15/2018 11:50:10 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1330

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
30

**Building Name**  
BUILDING A

**Abbrev**  
A

**Condition**  
Remodeling - C

**Fusion Room No**  
103E

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6420-Disabled Students Pr

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
75

**Measured Area**  
78.4

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**  
Desks

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/15/2018 11:50:10 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1340

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
30

**Building Name**  
BUILDING A

**Abbrev**  
A

**Condition**  
Remodeling - C

**Fusion Room No**  
107

**ROOM NAME**

**Status**  
Active

**Use Code**  
315-Office Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6770-Logistical Services

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
364

**Measured Area**  
336

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/15/2018 11:50:10 AM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1346

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
30

**Building Name**  
BUILDING A

**Abbrev**  
A

**Condition**  
Remodeling - C

**Fusion Room No**  
109C

**ROOM NAME**  
Workroom - copier

**Status**  
Active

**Use Code**  
315-Office Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6480-Veterans Services

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
60

**Measured Area**  
66.47

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/15/2018 11:50:10 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1348

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
30

**Building Name**  
BUILDING A

**Abbrev**  
A

**Condition**  
Remodeling - C

**Fusion Room No**  
109E

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6480-Veterans Services

**Assignable Stations**  
1

**Observed Stations**

**Assignable Area**  
136

**Measured Area**  
46.1

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
1

**Wall Finish**  
Paint

**Wall Condition**  
1

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/15/2018 11:50:10 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1363

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
102A

**ROOM NAME**  
Closet

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
7

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:31:58 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1366

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
103

**ROOM NAME**

**Status**  
Active

**Use Code**  
410-Read/Study Room

**Use Observed**  
See notes

**TOP/CSS Code**  
7010-Auxiliary Classes

**Assignable Stations**  
30

**Observed Stations**

**Assignable Area**  
973

**Measured Area**  
275

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This room is a lounge not a library space

**Fusion Recommendation**  
Reclassify Room to 650 Lounge

**Review Date**  
7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

**Id**  
1367

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
103A

**ROOM NAME**  
Activity Lab

**Status**  
Active

**Use Code**  
590-Other

**Use Observed**  
Unassigned

**TOP/CSS Code**  
7010-Auxiliary Classes

**Assignable Stations**  
20

**Observed Stations**  
16

**Assignable Area**  
384

**Measured Area**  
390

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
Carpet

**Floor Condition**  
1

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1377

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
108D

**ROOM NAME**  
Hallway

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
327

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sheet Vinyl

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:16:46 PM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1381

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
109F

**ROOM NAME**  
Office Hall

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
110

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:44:36 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1389

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
111A

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6220-Student Records, Stat

**Assignable Stations**  
1

**Observed Stations**  
2

**Assignable Area**  
243

**Measured Area**  
244.5

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:31:42 PM

# 1794 Room Assessment Data

**Id**  
1390

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
111B

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6220-Student Records, Stat

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
145

**Measured Area**  
145.6

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:31:42 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1404

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
116

**ROOM NAME**  
Men's Restroom

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
125

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Tile

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  
1410

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
120B

**ROOM NAME**  
Entry

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
491

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sheet Vinyl

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

**Id**  
1411

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
120

**ROOM NAME**  
Electrical

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
85

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
Exposed Structure

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id: 1422    Campus Name: Fresno City College    Campus Code: 571

Build No: 31    Building Name: STUDENT SERVICES    Abbrev: ST SER    Condition: Remodeling - C

Fusion Room No: 201A    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 6460-Financial Aid

Assignable Stations: 1    Observed Stations:

Assignable Area: 118    Measured Area: 117.18    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type: Desks

Floor Finish: Carpet    Floor Condition: 2

Ceiling Finish: ACT    Ceiling Condition: 1

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/3/2018 4:14:17 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1429

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
202A

**ROOM NAME**  
Supplies Storage

**Status**  
Active

**Use Code**  
730-Storage

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
4930-General Studies

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
38

**Measured Area**  
64

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
5

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1433

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
202H

**ROOM NAME**  
File Room

**Status**  
Active

**Use Code**  
315-Office Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6460-Financial Aid

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
203

**Measured Area**  
211.4

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
5

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 4:34:50 PM



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id: 1442    Campus Name: Fresno City College    Campus Code: 571

Build No: 31    Building Name: STUDENT SERVICES    Abbrev: ST SER    Condition: Remodeling - C

Fusion Room No: 205    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 6310-Counseling Services

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 98    Measured Area: 93.96    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type: Desks

Floor Finish: Carpet    Floor Condition: 3

Ceiling Finish: ACT    Ceiling Condition: 3

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/3/2018 4:46:23 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id: 1445    Campus Name: Fresno City College    Campus Code: 571

Build No: 31    Building Name: STUDENT SERVICES    Abbrev: ST SER    Condition: Remodeling - C

Fusion Room No: 207    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 6310-Counseling Services

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 98    Measured Area: 96.6    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type: Desks

Floor Finish: Carpet    Floor Condition: 2

Ceiling Finish: ACT    Ceiling Condition: 1

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id: 1453    Campus Name: Fresno City College    Campus Code: 571

Build No: 31    Building Name: STUDENT SERVICES    Abbrev: ST SER    Condition: Remodeling - C

Fusion Room No: 212    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 6310-Counseling Services

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 92    Measured Area: 85.47    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type: Desks

Floor Finish: Carpet    Floor Condition: 2

Ceiling Finish: ACT    Ceiling Condition: 4

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id: 1455    Campus Name: Fresno City College    Campus Code: 571

Build No: 31    Building Name: STUDENT SERVICES    Abbrev: ST SER    Condition: Remodeling - C

Fusion Room No: 214    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 6310-Counseling Services

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 92    Measured Area: 88.14    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type: Desks

Floor Finish: Carpet    Floor Condition: 3

Ceiling Finish: ACT    Ceiling Condition: 3

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1460

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
219

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6450-Student Personnel Ad

**Assignable Stations**  
2

**Observed Stations**

**Assignable Area**  
212

**Measured Area**  
254.28

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**  
Desks

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id: 1462    Campus Name: Fresno City College    Campus Code: 571

Build No: 31    Building Name: STUDENT SERVICES    Abbrev: ST SER    Condition: Remodeling - C

Fusion Room No: 220    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 6450-Student Personnel Ad

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 160    Measured Area: 161.7    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type: Desks

Floor Finish: Carpet    Floor Condition: 3

Ceiling Finish: ACT    Ceiling Condition: 4

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1465

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
222

**ROOM NAME**  
Office - Secretary to VP St. Services

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6450-Student Personnel Ad

**Assignable Stations**  
1

**Observed Stations**  
2

**Assignable Area**  
213

**Measured Area**  
198.36

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:16:46 PM



# 1794 Room Assessment Data

**Id**  
1466

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
223

**ROOM NAME**  
Women's Restroom

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
127

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Tile

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 4:03:55 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1468

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
224C

**ROOM NAME**  
Office Storage

**Status**  
Active

**Use Code**  
730-Storage

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6450-Student Personnel Ad

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
8

**Measured Area**  
8

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Wood

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

**Id**  
1469

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
224D

**ROOM NAME**  
Kitchenette

**Status**  
Active

**Use Code**  
655-Lounge Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6450-Student Personnel Ad

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
59

**Measured Area**  
70

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1471

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
225A

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6450-Student Personnel Ad

**Assignable Stations**  
2

**Observed Stations**  
4

**Assignable Area**  
566

**Measured Area**  
638

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1477

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
231

**ROOM NAME**  
Storage

**Status**  
Active

**Use Code**  
730-Storage

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6450-Student Personnel Ad

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
30

**Measured Area**  
30

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

**Id**  
1478

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
232

**ROOM NAME**

**Status**  
Active

**Use Code**  
350-Conference Room

**Use Observed**  
See notes

**TOP/CSS Code**  
6450-Student Personnel Ad

**Assignable Stations**  
5

**Observed Stations**  
1

**Assignable Area**  
113

**Measured Area**  
79.8

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This room is in office not conference

**Fusion Recommendation**  
Reclassify Room to 310 Office

**Review Date**  
7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

**Id**  
1479

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
232A

**ROOM NAME**

**Status**  
Active

**Use Code**  
315-Office Service

**Use Observed**  
See notes

**TOP/CSS Code**  
6450-Student Personnel Ad

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
113

**Measured Area**  
99.6

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This room is a telecom closet

**Fusion Recommendation**  
Reclassify Room715-DP/Computer Service

**Review Date**  
7/3/2018 7:16:46 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1481

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
31

**Building Name**  
STUDENT SERVICES

**Abbrev**  
ST SER

**Condition**  
Remodeling - C

**Fusion Room No**  
234

**ROOM NAME**  
Men's Restroom

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
146

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Tile

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 4:04:19 PM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  
1491

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
104A

**ROOM NAME**

**Status**  
Active

**Use Code**  
115-Classroom Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
26

**Measured Area**  
22

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This room is not close to service it is an electrical mechanical room

**Fusion Recommendation**

**Review Date**  
8/1/2018 5:44:36 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1493

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
106

**ROOM NAME**  
Janitor

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
FRP

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 5:45:04 PM

# 1794 Room Assessment Data

**Id**  
1494

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
106A

**ROOM NAME**  
Elev Mach

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 5:46:00 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1496

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
108

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
2201-Social Sciences, Gene

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
80.56

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 5:49:08 PM

# 1794 Room Assessment Data

Id **1497** Campus Name **Fresno City College** Campus Code **571**

Build No **32** Building Name **SOCIAL SCIENCE** Abbrev **SOCSCI** Condition **Remodeling - C**

Fusion Room No **109** ROOM NAME  Status **Active**

Use Code **310-Office** Use Observed **Matches Fusion** TOP/CSS Code **2201-Social Sciences, Gene**

Assignable Stations **1** Observed Stations **1**

Assignable Area **80** Measured Area **80.56** Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish **Carpet** Floor Condition **4**

Ceiling Finish **ACT** Ceiling Condition **3**

Wall Finish **Paint** Wall Condition **3**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date **8/1/2018 5:49:42 PM**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1500

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
111

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
2201-Social Sciences, Gene

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
82

**Measured Area**  
80.56

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 5:59:59 PM

# 1794 Room Assessment Data

**Id**  
1501

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
112

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
2201-Social Sciences, Gene

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
82

**Measured Area**  
80.56

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 5:59:59 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1504

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
115

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
2201-Social Sciences, Gene

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
82

**Measured Area**  
80.56

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 5:59:59 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  
1507

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
118A

**ROOM NAME**  
Men's Restroom

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
153

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Tile

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 6:01:20 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  
1515

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
123B

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6010-Academic Administra

**Assignable Stations**  
2

**Observed Stations**  
2

**Assignable Area**  
244

**Measured Area**  
246

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 6:14:19 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id **1518** Campus Name **Fresno City College** Campus Code **571**

Build No **32** Building Name **SOCIAL SCIENCE** Abbrev **SOCSCI** Condition **Remodeling - C**

Fusion Room No **125** ROOM NAME  Status **Active**

Use Code **315-Office Service** Use Observed **Matches Fusion** TOP/CSS Code **2201-Social Sciences, Gene**

Assignable Stations **1** Observed Stations

Assignable Area **82** Measured Area **80.56** Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish **Carpet** Floor Condition **4**

Ceiling Finish **ACT** Ceiling Condition **3**

Wall Finish **Paint** Wall Condition **4**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date **8/1/2018 6:22:24 PM**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1524

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
128A

**ROOM NAME**

**Status**  
Active

**Use Code**  
625-Exhibition Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6140-Museums and Galleri

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
109

**Measured Area**  
95.14

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 6:30:46 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1526

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
202

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
2201-Social Sciences, Gene

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
80.56

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 6:36:20 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1530

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
204

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
2201-Social Sciences, Gene

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
80

**Measured Area**  
80.56

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 6:38:47 PM



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1534

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
208

**ROOM NAME**

**Status**  
Active

**Use Code**  
110-Classroom

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
38

**Observed Stations**  
37

**Assignable Area**  
638

**Measured Area**  
624

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 6:48:52 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1538

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
211

**ROOM NAME**

**Status**  
Active

**Use Code**  
110-Classroom

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**  
32

**Observed Stations**  
30

**Assignable Area**  
513

**Measured Area**  
505

Unassigned areas were not required to be measured

**A/V Equip**  
Projector and Screen

**WhiteBoard**  
Yes

**Seating Type**  
Tables & Chairs

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 6:55:43 PM



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1541

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
212B

**ROOM NAME**  
Men's Restroom

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
148

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Tile

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Tile

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 7:00:30 PM

# 1794 Room Assessment Data

Id: 1542    Campus Name: Fresno City College    Campus Code: 571

Build No: 32    Building Name: SOCIAL SCIENCE    Abbrev: SOCSCI    Condition: Remodeling - C

Fusion Room No: 213    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 2201-Social Sciences, Gene

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 88    Measured Area: 88    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Carpet    Floor Condition: 3

Ceiling Finish: ACT    Ceiling Condition: 3

Wall Finish: Paint    Wall Condition: 2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 8/1/2018 7:02:18 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id: 1547    Campus Name: Fresno City College    Campus Code: 571

Build No: 32    Building Name: SOCIAL SCIENCE    Abbrev: SOCSCI    Condition: Remodeling - C

Fusion Room No: 218    ROOM NAME:    Status: Active

Use Code: 310-Office    Use Observed: Matches Fusion    TOP/CSS Code: 2201-Social Sciences, Gene

Assignable Stations: 1    Observed Stations: 1

Assignable Area: 84    Measured Area: 84.8    Unassigned areas were not required to be measured

A/V Equip:    WhiteBoard:    Seating Type:

Floor Finish: Carpet    Floor Condition: 4

Ceiling Finish: ACT    Ceiling Condition: 3

Wall Finish: Paint    Wall Condition: 3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects:

Assessment:

Fusion Recommendation:

Review Date: 8/1/2018 7:07:03 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1551

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
222

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
2201-Social Sciences, Gene

**Assignable Stations**  
2

**Observed Stations**  
2

**Assignable Area**  
282

**Measured Area**  
265.68

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 7:14:17 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1553

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
32

**Building Name**  
SOCIAL SCIENCE

**Abbrev**  
SOCSCI

**Condition**  
Remodeling - C

**Fusion Room No**  
223

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
2201-Social Sciences, Gene

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
84

**Measured Area**  
81.32

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 6:03:17 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1561

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
34

**Building Name**  
POLICE ACADEMY

**Abbrev**  
EULESS

**Condition**  
Remodeling - C

**Fusion Room No**  
PA1

**ROOM NAME**

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
2105-Administration of Jus

**Assignable Stations**  
5

**Observed Stations**  
5

**Assignable Area**  
490

**Measured Area**  
501.27

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/29/2018 5:41:12 PM

# 1794 Room Assessment Data

**Id**  
1562

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
34

**Building Name**  
POLICE ACADEMY

**Abbrev**  
EULESS

**Condition**  
Remodeling - C

**Fusion Room No**  
PA1A

**ROOM NAME**  
Office

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
2105-Administration of Jus

**Assignable Stations**  
5

**Observed Stations**  
3

**Assignable Area**  
406

**Measured Area**  
401.36

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/7/2018 3:55:32 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1564

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
34

**Building Name**  
POLICE ACADEMY

**Abbrev**  
EULESS

**Condition**  
Remodeling - C

**Fusion Room No**  
PA3

**ROOM NAME**  
Lounge

**Status**  
Active

**Use Code**  
655-Lounge Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
2105-Administration of Jus

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
123

**Measured Area**  
115.62

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/29/2018 5:39:27 PM



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1569

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
34

**Building Name**  
POLICE ACADEMY

**Abbrev**  
EULESS

**Condition**  
Remodeling - C

**Fusion Room No**  
PA7

**ROOM NAME**  
Cross Connect

**Status**  
Active

**Use Code**  
715-DP/Computer Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6780-Management Inform

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
83

**Measured Area**  
82.32

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/29/2018 5:49:20 PM

# 1794 Room Assessment Data

**Id**  
1570

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
34

**Building Name**  
POLICE ACADEMY

**Abbrev**  
EULESS

**Condition**  
Remodeling - C

**Fusion Room No**  
PA8

**ROOM NAME**  
Women's Restroom

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
177

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sheet Vinyl

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/29/2018 5:47:33 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1579

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
35

**Building Name**  
P E FIELD HOUSE

**Abbrev**  
PE FH

**Condition**  
Remodeling - C

**Fusion Room No**  
FH104

**ROOM NAME**  
Football Office w/student computer st

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**  
6

**Observed Stations**  
6

**Assignable Area**  
322

**Measured Area**  
326.26

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**  
Desks

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/29/2018 6:27:10 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1581

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
35

**Building Name**  
P E FIELD HOUSE

**Abbrev**  
PE FH

**Condition**  
Remodeling - C

**Fusion Room No**  
FH106

**ROOM NAME**  
Football office

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**  
1

**Observed Stations**  
1

**Assignable Area**  
143

**Measured Area**  
147

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/29/2018 6:28:46 PM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1584

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
35

**Building Name**  
P E FIELD HOUSE

**Abbrev**  
PE FH

**Condition**  
Remodeling - C

**Fusion Room No**  
FH107B

**ROOM NAME**  
Office service/refrigerator

**Status**  
Active

**Use Code**  
525-Athletic/Physical Ed Se

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
38

**Measured Area**  
36

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Tackboard

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/29/2018 7:16:36 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1589

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
35

**Building Name**  
P E FIELD HOUSE

**Abbrev**  
PE FH

**Condition**  
Remodeling - C

**Fusion Room No**  
FH108C

**ROOM NAME**  
Storage

**Status**  
Active

**Use Code**  
730-Storage

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
196

**Measured Area**  
196.56

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/29/2018 6:46:14 PM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1591

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
35

**Building Name**  
P E FIELD HOUSE

**Abbrev**  
PE FH

**Condition**  
Remodeling - C

**Fusion Room No**  
FH108M

**ROOM NAME**  
Storage Mezzanine

**Status**  
Active

**Use Code**  
730-Storage

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
397

**Measured Area**  
385

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Wood

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/29/2018 6:50:00 PM

# 1794 Room Assessment Data

**Id**  
1592

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
35

**Building Name**  
P E FIELD HOUSE

**Abbrev**  
PE FH

**Condition**  
Remodeling - C

**Fusion Room No**  
FH109

**ROOM NAME**  
Archery equipment & office

**Status**  
Active

**Use Code**  
525-Athletic/Physical Ed Se

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**  
1

**Observed Stations**  
2

**Assignable Area**  
225

**Measured Area**  
168

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
The room has been convert to an office

**Fusion Recommendation**

**Review Date**  
6/29/2018 6:54:44 PM

# 1794 Room Assessment Data

**Id**  
1593

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
35

**Building Name**  
P E FIELD HOUSE

**Abbrev**  
PE FH

**Condition**  
Remodeling - C

**Fusion Room No**  
FH110

**ROOM NAME**  
Soccer Coach Office

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**  
2

**Observed Stations**  
2

**Assignable Area**  
164

**Measured Area**  
156

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/29/2018 6:54:38 PM

# 1794 Room Assessment Data

**Id**  
1594

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
35

**Building Name**  
P E FIELD HOUSE

**Abbrev**  
PE FH

**Condition**  
Remodeling - C

**Fusion Room No**  
FH111

**ROOM NAME**  
Track Coach

**Status**  
Active

**Use Code**  
310-Office

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**  
2

**Observed Stations**  
2

**Assignable Area**  
125

**Measured Area**  
112.8

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
3

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/29/2018 6:57:03 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1596

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
35

**Building Name**  
P E FIELD HOUSE

**Abbrev**  
PE FH

**Condition**  
Remodeling - C

**Fusion Room No**  
FH112

**ROOM NAME**  
Janitor

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Tile

**Wall Condition**  
4

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/29/2018 7:00:21 PM

# 1794 Room Assessment Data

**Id**  
1597

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
35

**Building Name**  
P E FIELD HOUSE

**Abbrev**  
PE FH

**Condition**  
Remodeling - C

**Fusion Room No**  
FH113

**ROOM NAME**

**Status**  
Active

**Use Code**  
525-Athletic/Physical Ed Se

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
1705

**Measured Area**  
1736

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/29/2018 7:05:28 PM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1603

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
35

**Building Name**  
P E FIELD HOUSE

**Abbrev**  
PE FH

**Condition**  
Remodeling - C

**Fusion Room No**  
119

**ROOM NAME**  
Hallway

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/29/2018 7:11:18 PM

# 1794 Room Assessment Data

**Id**  
1605

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
37

**Building Name**  
UTILITY BUILDING

**Abbrev**  
UTIL

**Condition**  
Remodeling - C

**Fusion Room No**  
1

**ROOM NAME**  
Chiller Room

**Status**  
Active

**Use Code**  
770-Central Utility Plant

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6570-Utilities

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
3031

**Measured Area**  
3025

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Exposed Structure

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 11:05:49 AM

# 1794 Room Assessment Data

**Id**  
1606

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
37

**Building Name**  
UTILITY BUILDING

**Abbrev**  
UTIL

**Condition**  
Remodeling - C

**Fusion Room No**  
2

**ROOM NAME**  
Boiler

**Status**  
Active

**Use Code**  
770-Central Utility Plant

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
6570-Utilities

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
710

**Measured Area**  
676

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Exposed Structure

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 11:05:49 AM



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1613

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
39

**Building Name**  
CHILD DEV. LAB

**Abbrev**  
CDL

**Condition**  
Remodeling - C

**Fusion Room No**  
101

**ROOM NAME**

**Status**  
Active

**Use Code**  
555-Demonstration Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1305-Child Development/E

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
190

**Measured Area**  
189

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Tackboard

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This room is part of 110 office

**Fusion Recommendation**

**Review Date**  
8/10/2018 2:25:57 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1615

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
39

**Building Name**  
CHILD DEV. LAB

**Abbrev**  
CDL

**Condition**  
Remodeling - C

**Fusion Room No**  
103

**ROOM NAME**  
Staff Restroom

**Status**  
Active

**Use Code**  
315-Office Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1305-Child Development/E

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
115

**Measured Area**  
44.89

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sheet Vinyl

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
FRP

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
Room 103 is a staff Restroom

**Fusion Recommendation**

**Review Date**  
8/10/2018 2:32:48 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1618

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
39

**Building Name**  
CHILD DEV. LAB

**Abbrev**  
CDL

**Condition**  
Remodeling - C

**Fusion Room No**  
106A

**ROOM NAME**

**Status**  
Active

**Use Code**  
555-Demonstration Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1305-Child Development/E

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
75

**Measured Area**  
71.3

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sheet Vinyl

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
FRP

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 8:53:05 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1623

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
39

**Building Name**  
CHILD DEV. LAB

**Abbrev**  
CDL

**Condition**  
Remodeling - C

**Fusion Room No**  
110

**ROOM NAME**  
Break Room/Storage

**Status**  
Active

**Use Code**  
555-Demonstration Service

**Use Observed**  
See notes

**TOP/CSS Code**  
1305-Child Development/E

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
828

**Measured Area**  
837

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**  
This is staff break room

**Fusion Recommendation**  
Reclassify Room to 650 - Lounge

**Review Date**  
8/10/2018 8:53:05 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1627

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
40

**Building Name**  
CHILD DEV LAB 2

**Abbrev**  
CD 2

**Condition**  
Remodeling - A

**Fusion Room No**  
1C

**ROOM NAME**  
Staff Restroom

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
48

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sheet Vinyl

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
FRP

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 8:53:05 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1631

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
40

**Building Name**  
CHILD DEV LAB 2

**Abbrev**  
CD 2

**Condition**  
Remodeling - A

**Fusion Room No**  
1F

**ROOM NAME**  
Kitchen Appliance Storage

**Status**  
Active

**Use Code**  
635-Food Facilities Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
1305-Child Development/E

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
42

**Measured Area**  
40

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sheet Vinyl

**Floor Condition**  
3

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/10/2018 8:53:05 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1640

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
46

**Building Name**  
GROUNDS BUILDING

**Abbrev**  
GRNDS1

**Condition**  
Remodeling - C

**Fusion Room No**  
1B

**ROOM NAME**

**Status**  
Active

**Use Code**  
525-Athletic/Physical Ed Se

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0835-Physical Education

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
250

**Measured Area**  
326.6

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
1

**Ceiling Finish**  
Paint

**Ceiling Condition**  
2

**Wall Finish**  
Paint

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
6/29/2018 6:06:35 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1647

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
48

**Building Name**  
RATCLIFFE RESTROOM 2

**Abbrev**  
RR 2

**Condition**  
Remodeling - C

**Fusion Room No**  
1

**ROOM NAME**  
Ratcliffe Restroom 2

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
410

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Tile

**Wall Condition**  
4

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 2:48:35 PM

# 1794 Room Assessment Data

**Id**  
1648

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
48

**Building Name**  
RATCLIFFE RESTROOM 2

**Abbrev**  
RR 2

**Condition**  
Remodeling - C

**Fusion Room No**  
2

**ROOM NAME**  
Ratcliffe Restroom 2

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
425

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Tile

**Wall Condition**  
4

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 2:48:44 PM

# 1794 Room Assessment Data

**Id**  
1649

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
48

**Building Name**  
RATCLIFFE RESTROOM 2

**Abbrev**  
RR 2

**Condition**  
Remodeling - C

**Fusion Room No**  
3

**ROOM NAME**  
Janitor

**Status**  
Non-assignable

**Use Code**  
-

**Use Observed**  
Unassigned

**TOP/CSS Code**  
-

**Assignable Stations**

**Observed Stations**

**Assignable Area**

**Measured Area**  
0

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Sealed Concrete

**Floor Condition**  
2

**Ceiling Finish**  
Paint

**Ceiling Condition**  
3

**Wall Finish**  
Paint

**Wall Condition**  
3

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
7/3/2018 2:48:54 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  
1660

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
57

**Building Name**  
FORUM HALL

**Abbrev**  
FH

**Condition**  
Remodeling - C

**Fusion Room No**  
102

**ROOM NAME**  
Lecture

**Status**  
Active

**Use Code**  
115-Classroom Service

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
866

**Measured Area**  
858

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
4

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 7:37:48 PM

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

Id  Campus Name  Campus Code

Build No  Building Name  Abbrev  Condition

Fusion Room No  ROOM NAME  Status

Use Code  Use Observed  TOP/CSS Code

Assignable Stations  Observed Stations

Assignable Area  Measured Area  Unassigned areas were not required to be measured

A/V Equip  WhiteBoard  Seating Type

Floor Finish  Floor Condition

Ceiling Finish  Ceiling Condition

Wall Finish  Wall Condition

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

Observed Defects

Assessment

Fusion Recommendation

Review Date



# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1666

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
57

**Building Name**  
FORUM HALL

**Abbrev**  
FH

**Condition**  
Remodeling - C

**Fusion Room No**  
202

**ROOM NAME**  
Storage

**Status**  
Active

**Use Code**  
730-Storage

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
0099-General Assignment

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
352

**Measured Area**  
312

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
VCT

**Floor Condition**  
4

**Ceiling Finish**  
ACT

**Ceiling Condition**  
4

**Wall Finish**  
Paint

**Wall Condition**  
4

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
8/1/2018 7:40:47 PM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**

# 1794 Room Assessment Data

**Id**  
1669

**Campus Name**  
Fresno City College

**Campus Code**  
571

**Build No**  
58

**Building Name**  
POLICE ACAD ST LOUNGE

**Abbrev**  
PASL

**Condition**  
Satisfactory

**Fusion Room No**  
PA11

**ROOM NAME**  
Student Lounge

**Status**  
Active

**Use Code**  
650-Lounge

**Use Observed**  
Matches Fusion

**TOP/CSS Code**  
2105-Administration of Jus

**Assignable Stations**

**Observed Stations**

**Assignable Area**  
889

**Measured Area**  
889.2

Unassigned areas were not required to be measured

**A/V Equip**

**WhiteBoard**

**Seating Type**

**Floor Finish**  
Carpet

**Floor Condition**  
2

**Ceiling Finish**  
ACT

**Ceiling Condition**  
2

**Wall Finish**  
Tackboard

**Wall Condition**  
2

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**  
9/3/2018 11:49:05 AM

# 1794 Room Assessment Data

**Id**  **Campus Name**  **Campus Code**

**Build No**  **Building Name**  **Abbrev**  **Condition**

**Fusion Room No**  **ROOM NAME**  **Status**

**Use Code**  **Use Observed**  **TOP/CSS Code**

**Assignable Stations**  **Observed Stations**

**Assignable Area**  **Measured Area**  Unassigned areas were not required to be measured

**A/V Equip**  **WhiteBoard**  **Seating Type**

**Floor Finish**  **Floor Condition**

**Ceiling Finish**  **Ceiling Condition**

**Wall Finish**  **Wall Condition**

- 1 New-New or like-new condition; no issues to report; no expected failures; Plan 8 to 10 Yrs.
- 2 Good - Good condition; no reported issues or concerns; consider replacement 6 to 8 Yrs.
- 3 Fair Average wear for building age; not new but no issues to report; replace within 4 to 6 Yrs.
- 4 Poor - Worn from use - at the end of expected lifecycle . Replace within 2 - 4 years.
- 5 Critical Extremely worn or damaged; replace in next 2 Yrs

**Observed Defects**

**Assessment**

**Fusion Recommendation**

**Review Date**